

**COUNTY OF LOS ANGELES**

**ROAD DEPARTMENT**



**MALIBU QUAD**

**BENCH MARKS**

**1960**

## PREFACE

The Road Department level net is composed of more than 1,000 miles of levels supporting in excess of 10,000 bench marks. In 1964-65, a major readjustment of the net was undertaken. To emphasize the complete break with previous elevations, the SY, SG & SL series bench marks have been re-labeled BY, BG & BL, respectively.

To facilitate the adjustment, indexing, and distribution of adjusted values of the net, the County territory was divided into 31 quads or areas. For identification purposes each quad was given a name, viz., "Rosemead," "La Mirada," "Santa Fe," etc. When bench marks and elevations in the Road Department net are used, the name of the quad in which the bench mark is located and the date of the adjustment of the elevation must be included in the bench mark description, e.g.,

BG 1887 --L+BN IN CONC HDWL OF DRAIN PIPE UNDER DR 218 FT  
NE +18 FT SE C/L INT SAN JOSE HILLS RD +CAMERON AVE MKD (BM)  
( COVINA --1965) ELEV. 696.238

It is expected that this general adjustment will, for the most part, remain sound for the next 8 to 12 years. As new circuits are completed, however, re-adjustment of individual quads may become advisable. It is expected that these subsequent adjustments will be in the nature of a few hundredths of a foot. When a quad is re-adjusted, new elevation lists will be published and the date of the re-adjustment will replace the "1965" at the end of the bench mark description. Two bench marks in the same quad with different adjustment dates will not normally join each other. Since all adjustments taper out to nothing at the periphery of the quad, any bench mark in one quad will join any bench mark in another quad regardless of their respective adjustment dates.

The basic accuracy of the net is reflected by an indicated field probable error of plus or minus 0.012 foot per mile of leveling as determined from 298 conditions of closure. However, many years experience in vertical control in the greater Los Angeles basin and Antelope Valley indicate that because of varying degrees of subsidence and heaving, the true datum is recovered only by obtaining substantial agreement of a number of bench marks.

The users of this net are invited to assist in its maintenance by notifying this Department of cases of obliteration, apparent mistakes in descriptions or elevations, and proven disturbance of bench marks.

---


DATUM: U. S. Coast and Geodetic Survey Sea Level Datum  
of 1929, through the medium of the Los Angeles  
County Engineer Precise Level Net, 1963 Adjust-  
ment.

ABBREVIATIONS USED IN BENCH MARK LISTINGS

|                     |                           |                      |                                       |
|---------------------|---------------------------|----------------------|---------------------------------------|
| ABUT - - - - -      | Abutment                  | EC - - - - -         | End of Curve                          |
| ALG - - - - -       | Along                     | ENT - - - - -        | Entrance                              |
| ANG PT - - - - -    | Angle Point               | FL - - - - -         | Floor                                 |
| B/W - - - - -       | Back of Walk              | FTG - - - - -        | Footing                               |
| BCR - - - - -       | Beginning of Curb Return  | F/W - - - - -        | Front of Walk                         |
| BC - - - - -        | Beginning of Curve        | GAR - - - - -        | Garage                                |
| BLDG - - - - -      | Building                  | HDWL - - - - -       | Headwall                              |
| BM - - - - -        | Bench Mark                | HSE - - - - -        | House                                 |
| BT SPK - - - - -    | Boat or Bolt Spike        | INT - - - - -        | Intersection                          |
| BR CAP - - - - -    | Brass or Bronze Cap       | IP - - - - -         | Iron Pipe                             |
| C B - - - - -       | Catch Basin               | LT - - - - -         | Left                                  |
| CTR - - - - -       | Center                    | LACE - - - - -       | L. A. City Engineer                   |
| C/L - - - - -       | Center Line               | LACS - - - - -       | L. A. County Engineer                 |
| C/L INT - - - - -   | Center Line Intersection  | LAFC - - - - -       | L. A. Co. Flood Control               |
| C/L PROD - - - - -  | Center Line Produced      | L+BN - - - - -       | Lead and Bench Nail                   |
| CONC - - - - -      | Concrete                  | L+BR - - - - -       | Lead and Brad                         |
| COR - - - - -       | Corner                    | L+N - - - - -        | Lead and Nail                         |
| COE - - - - -       | Corps of Engineers        | L+RDBM TAG - - - - - | Lead and Road Dept. Bench<br>Mark Tag |
| CULV - - - - -      | Culvert                   | L+SPK - - - - -      | Lead and Spike                        |
| CB - - - - -        | Curb                      | L+T - - - - -        | Lead and Tack                         |
| CS MON - - - - -    | County Engineer Monument  | MCR - - - - -        | Middle of Curb Return                 |
| CS BR CAP - - - - - | County Engineer Brass Cap | MKD - - - - -        | Marked                                |
| CT SPK - - - - -    | Cut Spike                 | MC - - - - -         | Middle of Curve                       |
| DR - - - - -        | Drive or Driveway         | MON - - - - -        | Monument                              |
| E/O - - - - -       | East of                   | N/O - - - - -        | North of                              |
| ECR - - - - -       | End of Curb Return        | NR - - - - -         | Near                                  |

ABBREVIATIONS USED IN BENCH MARK LISTINGS . . . CONTINUED

OPP - - - - - Opposite  
PI - - - - - Point of Intersection  
PK+W - - - - - PK Nail and Washer  
P/L - - - - - Property Line  
POST - - - - - Point on Semi-Tangent  
PP - - - - - Power Pole  
PVMT - - - - - Pavement  
PROD - - - - - Produced  
RD - - - - - Road  
RDEM - - - - - Road Dept. Bench Mark  
RR - - - - - Railroad  
RT - - - - - Right  
R/W - - - - - Right of Way  
SDMH - - - - - Storm Drain Manhole  
SMH - - - - - Sewer Manhole  
SPK - - - - - Spike  
ST+W - - - - - Spike Tin and Washer  
S/O - - - - - South of  
TP - - - - - Telephone Pole  
USC+GS - - - - - U. S. Coast and Geodetic Survey  
USGS - - - - - U. S. Geological Survey  
WK - - - - - Walk  
W/O - - - - - West of



| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM NUMBER |
|------------------|----------|--|-----------|
| MALIBU<br>(1960) | 920.622  | ST HWY MON IN WELL C/L LONG VALLEY RD (VENTURA FRWY N SERVICE RD) 90FT± W C/L VALLEY CIRCLE BLVD   | SY 4925   |
| MALIBU<br>(1960) | 922.452  | RDBM TAG N CB LONG VALLEY RD (N SERVICE RD VENTURA FRWY) UNDER MULHOLLAND DR OVERCROSSING @ APPROX C/L MULHOLLAND DR   | SY 4926   |
| MALIBU<br>(1960) | 926.680  | BR CAP C/L VENTURA FRWY 12IN DN 1200FT W MULHOLLAND DR OVERCROSSING  | SY 4927   |
| MALIBU<br>(1960) | 926.098  | FLAG WIRE SPK N CB VENTURA FRWY N SERVICE RD 73FT W LONG VALLEY RD PROD FROM NW (ENT RD TO HIDDEN HILLS) 105FT N C/L VENTURA FRWY  | SY 4928   |
| MALIBU<br>(1960) | 920.634  | RDBM TAG CONC CB 5FT± SE GUARD HSE @ ENT TO HIDDEN HILLS 2FT± N C/L LONG VALLEY RD (PRIVATE RD)  | SY 4929   |
| MALIBU<br>(1960) | 938.361  | RDBM TAG E CB PARADISE VALLEY RD 5FT N CB RET @ NE COR LONG VALLEY RD 45FT N + 15FT E C/L INT 3.5MI± NW VENTURA FRWY   | SY 4930   |
| MALIBU<br>(1960) | 938.518  | RDBM TAG N CB LONG VALLEY RD 5FT W CB RET @ NW COR PARADISE VALLEY RD 18FT± N + 45FT W C/L INT   | SY 4931   |
| MALIBU<br>(1960) | 973.684  | RDBM TAG E CB HILLTOP RD 1FT S CB RET @ NE COR LONG VALLEY RD 45FT± N + 13FT± E C/L INT  | SY 4932   |
| MALIBU<br>(1960) | 973.668  | RDBM TAG W CB HILLTOP RD 1FT± S CB RET @ NW COR LONG VALLEY RD 45FT± N + 13FT± W C/L INT   | SY 4933   |
| MALIBU<br>(1960) | 1029.286 | RDBM TAG NR NE COR CONC SLAB @ HILLEN HILLS MUTUAL WATER CO WELL NO U8 40FT E C/L ROUND MEADOW RD + 95FT± S C/L LONG VALLEY RD   | SY 4934   |
| MALIBU<br>(1960) | 1030.821 | L+T CONC WK TO HSE NO 24655 55FT E + 145FT N C/L INT ROUND MEADOW RD + WING FIELD RD   | SY 4935   |
| MALIBU<br>(1960) | 1104.194 | L+T S EDGE CONC DRWY HSE NO 5404 ROUND MEADOW RD 21FT E C/L ROUND MEADOW RD + 185FT± N C/L HOBACK GLEN RD  | SY 4936   |
| MALIBU<br>(1960) | 1098.269 | L+T E EDGE CONC DRWY S/S HSE NO 5404 ROUND MEADOW RD 20FT± N C/L HOBACK GLEN RD + 83FT± E C/L ROUND MEADOW RD  | SY 4937   |
| MALIBU<br>(1960) | 1102.132 | RDBM TAG NW COR 30IN BY 30IN CONC SQUARE 40FT± E C/L ROUND MEADOW RD 20FT± N TRACT LINE (HIDDEN HILLS) 0.4 MI± N VENTURA FRWY  | SY 4938   |
| MALIBU<br>(1960) | 1107.666 | RDBM TAG NE COR CONC SLAB 58FT W C/L ROUND MEADOW RD 12FT± N END PAVED RD @ TRACT LINE (HIDDEN HILLS) 0.4MI± N VENTURA FRWY  | SY 4939   |
| MALIBU<br>(1960) | 1094.980 | RR SPK NE SIDE 30IN OAK TREE 6IN ABOVE GROUND 115FT± S C/L VENTURA FRWY 0.6MI± W MULHOLLAND DR   | SY 4940   |
| MALIBU<br>(1960) | 1090.980 | ST HWY BR CAP 8IN DN ON VENTURA ON VENTURA FRWY C/L @ BC 0.6MI± W MULHOLLAND DR  | SY 4941   |
| MALIBU<br>(1960) | 1124.088 | CS BR CAP 6IN ABOVE SURFACE IN 12IN CONC POST 4FT W TP NO 588165H ON N TOPANGA CANYON BLVD 1.5MI± S VENTURA BLVD NR MI MARKER (A-10.95MI) 50FT± SE C/L N TOPANGA CANYON BLVD MKD (BM 56-19 RE 5869 1960) | SY 5324   |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM | NUMBER |
|------------------|----------|--|----|--------|
| MALIBU<br>(1960) | 1015.804 | FD HEX BT IN LACE MON 10IN DN IN WELL ON APPROX<br>C/L MULHOLLAND DR + C/L PROD TOPANGA CANYON BLVD<br>TO THE S  | SY | 5325   |
| MALIBU<br>(1960) | 1046.464 | RDBM TAG E WINGWALL ROCK CULV 1FT S OF N END<br>160FT S APPROX C/L INT MULHOLLAND DR<br>+ MULHOLLAND HWY 0.5MI± W TOPANGA CANYON BLVD  | SY | 5328   |
| MALIBU<br>(1960) | 1070.422 | RDBM TAG @ SW COR CONC + ROCK CULV 25FT± N C/L<br>MULHOLLAND HWY + APPROX 400FT W<br>DECLARATION AVE   | SY | 5332/  |
| MALIBU<br>(1960) | 1042.724 | RDBM TAG CTR HDWL OVER DRAIN PIPE OF CULV 15FT±<br>E APPROX C/L INT OLD TOPANGA CANYON RD +<br>MULHOLLAND HWY 2FT E POST (408+38)  | SY | 5333   |
| MALIBU<br>(1960) | 1104.117 | RDBM TAG E WINGWALL CONC + ROCK CULV 4FT S<br>OF END OF WINGWALL 20FT± S C/L MULHOLLAND HWY +<br>0.5MI± SW INT OLD TOPANGA CANYON RD +<br>MULHOLLAND HWY TO THE N  | SY | 5335   |
| MALIBU<br>(1960) | 1114.007 | L+T CTR CONC + ROCK HDWL CULV 25FT± N C/L<br>MULHOLLAND HWY + 0.6MI± SW INT OLD TOPANGA<br>CANYON RD + MULHOLLAND HWY @ MARKER POST<br>*328+31)  | SY | 5336   |
| MALIBU<br>(1960) | 1191.016 | RDBM TAG E CONC + ROCK HDWL 2FT± S OF N END<br>23FT± S C/L MULHOLLAND HWY + 540FT± E INT<br>DRY CANYON COLD CR RD TO THE W 0.9MI± SW INT<br>OLD TOPANGA CN RD + MULHOLLAND HWY   | SY | 5337   |
| MALIBU<br>(1960) | 1197.255 | RDBM TAG SE COR CONC WINGWALL CULV 20FT± NW C/L<br>MULHOLLAND HWY + 200FT± E INT DRY CN COLD CR<br>RD TO THE W + 1.0MI± SW INT OLD TOPANGA CN RD<br>+ MULHOLLAND HWY + 33FT± E HWY MARKER (355+32)                         | SY | 5338   |
| MALIBU<br>(1960) | 1279.418 | RDBM TAG S CONC + ROCK WINGWALL CULV 20FT± W<br>+ 35FT± N APPROX C/L INT MULHOLLAND HWY +<br>CANYON DR TO THE E 1.5MI± SW OLD TOPANGA CN RD  | SY | 5339   |
| MALIBU<br>(1960) | 1285.853 | RDBM TAG CTR CONC + ROCK HDWL CULV 32FT± E +<br>28FT± S APPROX C/L INT MULHOLLAND HWY + CANYON<br>DR TO THE E NR HWY MARKER *333+90) 1.5MI± SW<br>OLD TOPANGA CN RD  | SY | 5340   |
| MALIBU<br>(1960) | 1458.554 | RDBM TAG SE COR CONC EQUESTRIAN TUNNEL 15FT±<br>N C/L DRY CN COLD CR RD 0.1MI± W C/L INT<br>MULHOLLAND HWY + DRY CN COLD CR RD TO THE W NR<br>HWY MARKER (102+55) (2.0MI± SW OLD<br>TOPANGA CN RD)                         | SY | 5341   |
| MALIBU<br>(1960) | 1457.972 | RDBM TAG CTR CONC + ROCK HDWL TO EQUESTRIAN<br>TUNNEL 15FT± S C/L DRY CN COLD CR RD 0.1MI± W<br>C/L INT MULHOLLAND HWY + DRY CN COLD CR RD TO<br>THE W ACROSS RD FROM HWY MARKER (102+55)<br>(2.0MI± SW OLD TOPANGA CN RD) | SY | 5342   |
| MALIBU<br>(1960) | 1394.080 | RDBM TAG N WINGWALL CONC + ROCK CULV 15FT± E<br>C/L DRY CN COLD CR RD ACROSS RD FROM HWY MARKER<br>(83+36) +0.4MI± SW FROM C/L INT DRY CN COLD CR<br>RD + MULHOLLAND HWY   | SY | 5343   |
| MALIBU<br>(1960) | 1344.701 | RDBM TAG N WINGWALL CONC + ROCK CULV 15FT± E<br>C/L DRY CN COLD CR RD 0.65MI± SW FROM INT DRY<br>CN COLD CR RD + MULHOLLAND HWY  | SY | 5344   |
| MALIBU<br>(1960) | 1335.239 | RDBM TAG N WINGWALL CONC + ROCK CULV 15FT± E<br>C/L DRY CN COLD CR RD 0.65MI± SW FROM INT DRY<br>CN COLD CR RD + MULHOLLAND HWY  | SY | 5345   |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 1326.813 | CS BM MON CONC BASE 6IN ABOVE SURFACE 28FT W<br>C/L DRY CN COLD CR RD + 0.7MI± SW C/L INT OF<br>DRY CN COLD CR RD + MULHOLLAND HWY MKD (BM 9M<br>RE 2177) 25FT± SW HWY MARKER (68+13) | SY 5346   |
| MALIBU<br>(1960) | 1235.344 | RDBM TAG S WINGWALL OF CONC + ROCK CULV 15FT± E<br>C/L DRY CN COLD CR RD + 1.25 MI± SW C/L INT<br>DRY CN COLD CR RD + MULHOLLAND HWY  | SY 5347   |
| MALIBU<br>(1960) | 1213.405 | RDBM TAG N WINGWALL CONC + ROCK CULV 15FT E<br>C/L DRY CN C/LD CR RD + 1.26MI± SW C/L INT<br>DRY CN COLD CR RD + MULHOLLAND HWY NR HWY MARKER<br>(36+84)                              | SY 5348   |
| MALIBU<br>(1960) | 1164.729 | RDBM TAG N WINGWALL CONC + ROCK CULV 15FT± E<br>C/L DRY CN COLD CR RD + 1.7MI± SW COL INT<br>DRY CN COLD CR RD + MULHOLLAND HWY NR HWY MARKER   | SY 5349   |
| MALIBU<br>(1960) | 1152.297 | RDBM TAG W WINGWALL CONC + ROCK CULV 15FT± N<br>C/L DRY CN COLD CR RD + 1.8MI± S C/L INT<br>DRY CN COLD CR RD + MULHOLLAND HWY 70FT± SE HWY<br>MARKER (15+84)                         | SY 5350   |
| MALIBU<br>(1960) | 1058.328 | RDBM TAG N WINGWALL CONC + ROCK CULV 20FT± W<br>C/L MULHOLLAND HWY 650FT S C/L INT DRY CN COLD<br>CR RD TO THE W + MULHOLLAND HWY 10FT± S<br>PP NO 1090729E 0.15MI± N STUNT RD        | SY 5352   |
| MALIBU<br>(1960) | 1028.131 | RDBM TAG E WINGWALL 20FT± N + 65FT W C/L INT<br>MULHOLLAND HWY + COLD CN RD TO THE SE NR HWY<br>MARKER (198+01) 0.4MI± SW STUNT RD  | SY 5353   |
| MALIBU<br>(1960) | 1024.246 | RDBM TAG CTR HDWL CONC + ROCK CULV 30FT± S +<br>70FT± W C/L INT MULHOLLAND HWY + COLD CN RD TO<br>THE SE ACROSS FROM HWY MARKER (198+01) 0.4MI± SW<br>STUNT RD                        | SY 5354   |
| MALIBU<br>(1960) | 975.124  | RDBM TAG NE WINGWALL CONC + ROCK CULV 20FT± SE<br>C/L MULHOLLAND HWY 300FT± N C/L INT COLD CN RD +<br>MULHOLLAND HWY 70FT± S TP NO 713575H 1.0MI± SW<br>STUNT RD                      | SY 5355   |
| MALIBU<br>(1960) | 964.114  | CS BR CAP CONC POST 6IN ABOVE SURFACE 320FT± S<br>C/L MULHOLLAND HWY 16FT± E C/L COLD CYN RD<br>1.0MI± SW STUNT RD 4FT± S PP NO 711130E MKD<br>(BM M5H RE 329)                        | SY 5356   |
| MALIBU<br>(1960) | 721.520  | RDBM TAG CONC BOULDER 20FT± E C/L COLD CN RD<br>35FT± SE FROM HWY MARKER (75+30) 95FT SE FROM<br>PP NO 711120E 0.6MI± S C/L INT COLD CN RD +<br>MULHOLLAND HWY NR PRVT RD TO E        | SY 5358   |
| MALIBU<br>(1960) | 735.594  | RDBM TAG IN S WINGWALL CONC + ROCK CULV 16FT± W<br>C/L COLD CN RD 95FT± NW HWY MARKER (58+29) 80FT±<br>N PP NO 711113E 1.0MI± S C/L INT COLD CN RD +<br>MULHOLLAND HWY                | SY 5359   |
| MALIBU<br>(1960) | 631.138  | RDBM TAG NR N END OF CULV CONC HDWL 18FT± E<br>C/L COLD CN RD + 165FT± SE WONDerview DR 10FT± N<br>HWY MARKER (32+71) 1.5MI± S MULHOLLAND HWY   | SY 5361   |
| MALIBU<br>(1960) | 609.553  | RDBM TAG NR CTR CULV CONC HDWL 18FT W C/L<br>COLD CN RD + 340FT± S WOODBLUFF DR NR HWY MARKER<br>(7+31) 2.0MI± S MULHOLLAND HWY + COLD CN RD INT                                      | SY 5363   |
| MALIBU<br>(1960) | 612.038  | RDBM TAG @ ANGLE PT IN CULV CONC HDWL 20FT± SE<br>C/L COLD CN RD + 520FT± S WOODBLUFF DR NR HWY<br>MARKER (5+53) 2.0MI± S MULHOLLAND HWY + COLD CN<br>RD INT                          | SY 5364   |



| QUAD-YEAR        | ELEV    | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM NUMBER |
|------------------|---------|--|-----------|
| MALIBU<br>(1960) | 460.188 | SPK+W CTR CULV RUBBLE HDWL 12FT± NW C/L PIUMA RD + 300FT± E CRATER CAMP DR 0.4MI± E LAS VIRGENES RD NR HWY MARKER (321+36)   | SY 5365   |
| MALIBU<br>(1960) | 470.863 | CS BM MON IN CONC ABUT @ NW COR BRIDGE NO B 989 MALIBU CN RD (LAS VIRGENES RD) 15FT± W C/L MALIBU CN RD + 180FT± S C/L PIUMA RD MKD (BM 57-13 1960RD 58 69)  | SY 5367   |
| MALIBU<br>(1960) | 40.030  | LACE MON IN WELL 12IN BELOW SURFACE 26FT± S C/L PACIFIC COAST HWY 0.1MI± E LAC LIMITS 38FT±E OF W EDGE OF CONC STEPS TO BEACH 76FT± S OF W EDGE OF CONC RET WALL @ N CB MKD (TOPANGA CANYON E-7)     | SY 5368   |
| MALIBU<br>(1960) | 21.200  | LACE HEX BAR IN WELL 18IN BELOW SURFACE C/L PACIFIC COAST HWY @ J. PAUL GETTY MUSEUM OPP DOOR TO BLDG NO 18002 52FT SE OF W END ROCK WALL + 37FT± SW OF SPK IN CATCH BASIN                           | SY 5369   |
| MALIBU<br>(1960) | 19.292  | CS TRAVERSE MON PACIFIC COAST HWY OPP W LINE HSE NO 18222 2FT± S OF N EDGE OF PVMT 58FT± N OF NW COR HSE MKD (D-8)   | SY 5370   |
| MALIBU<br>(1960) | 20.360  | CS TRAVERSE MON PACIFIC COAST HWY 0.2MI± E TOPANGA CANYON BLVD 4FT± N OF S SIDE PVMT 45FT± NW OF PP NO 1085812E 82FT± NE OF PP NO 880862E MKD (C-8B)   | SY 5371   |
| MALIBU<br>(1960) | 28.753  | USC+GS MON ON TOP CONC POST PACIFIC COAST HWY + TOPANGA CREEK @ SE COR OF CONC BRIDGE OUTSIDE OF E END OF GUARD RAIL MKD (P-99, 1933)  | SY 5372   |
| MALIBU<br>(1960) | 28.750  | CS TRAVERSE MON IN WELL PACIFIC COAST HWY @ TOPANGA CN BRIDGE 11FT± S OF S EDGE MAC PVMT 103FT W L+T CB S SIDE BRIDGE MKD (N-72)   | SY 5373   |
| MALIBU<br>(1960) | 21.334  | CS TRAVERSE MON IN WELL PACIFIC COAST HWY 380FT± E TUNA CANYON RD 3FT± S OF EDGE OF MAC PVMT 20FT± NW OF NW COR OF HSE NO 18976 MKD (TCB-8A)   | SY 5374   |
| MALIBU<br>(1960) | 20.383  | CSBM MON N EDGE PVMT PACIFIC COAST HWY FRONT OF HSE NO 19214 80FT± NW PP NO 770783E + 89FT± NE OF PP NO 1027877E   | SY 5375   |
| MALIBU<br>(1960) | 21.779  | CS BR DISC CTR N HDWL PACIFIC COAST HWY @ BRIDGE OVER PENA CANYON + 25FT SE ENT HSE NO 19355   | SY 5376   |
| MALIBU<br>(1960) | 21.629  | USC+GS MON SE COR ANG HDWL CULV PACIFIC COAST HWY 0.6MI± W TUNA CYN RD + 165FT± W OF ENT TO BUDWOOD RANCHO (HSE NO 19453) MKD (L-576 1939)   | SY 5377   |
| MALIBU<br>(1960) | 27.048  | CS TRAVERSE MON IN WELL 29FT± N C/L PACIFIC COAST HWY 1.3MI± W OF TOPANGA CREEK BRIDGE 8FT± N OF N EDGE OF THE MAC PVMT 164FT± E CATCH BASIN ON N SIDE PACIFIC COAST HWY MKD (LAS FLORES L-8A, 1947) | SY 5378   |
| MALIBU<br>(1960) | 26.246  | CS TRAVERSE MON PACIFIC COAST HWY 1.6MI± W TOPANGA CANYON CREEK BRIDGE 3FT± S OF S EDGE OF MAC PVMT OPP CULV NO 82+76 MKD (LAS FLORES L-8A 1947)   | SY 5379   |
| MALIBU<br>(1960) | 21.130  | USC+GS MON TOP N HDWL CULV NO 47+25 ON PACIFIC COAST HWY 3.7MI± W OF CASTELLAMMARE BRIDGE 1FT± W OF E END OF BRIDGE MKD (M576 1939)  | SY 5380   |
| MALIBU<br>(1960) | 24.210  | CS TRAVERSE MON 3FT± N OF N EDGE PVMT PACIFIC COAST HWY 20FT E GARAGE BELONGING TO HSE NO 20705 51FT± SW TP NO 936614E MKD (LAS FLORES J-8A)   | SY 5381   |

| QUAD-YEAR        | ELEV    | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM NUMBER |
|------------------|---------|--|-----------|
| MALIBU<br>(1960) | 31.040  | CS TRAVERSE MON PACIFIC COAST HWY 79FT± NE OF NE COR OF HSE NO 20932 52FT± E OF GUY POLE MKD (LAS FLORES I-8, 1947)  | SY 5382   |
| MALIBU<br>(1960) | 17.721  | USC+GS MON TOP SE END RETAINING WALL PACIFIC COAST HWY @ LAS FLORES CANYON BRIDGE 1FT± NW OF NW END OF N GUARD RAIL CONC BRIDGE MKD (N-576 1939)                 | SY 5383   |
| MALIBU<br>(1960) | 15.129  | CS TRAVERSE MON IN WELL 15FT± S OF N CB PACIFIC COAST HWY 59FT± E OF E LINE OF HSE NO 21628 MKD (LAS FLORES 6-8A)  | SY 5384   |
| MALIBU<br>(1960) | 15.355  | BT N CB PACIFIC COAST HWY @ COAL CANYON (CARBON CANYON) CTR BRIDGE NO 53-33  | SY 5385   |
| MALIBU<br>(1960) | 18.749  | USC+GS MON 0.8FT± E OF W ANG PT IN CONC RAILING BRIDGE ON PACIFIC COAST HWY @ COAL CANYON (CARBON CANYON) MKD (B 1052 1960)                                      | SY 5386   |
| MALIBU<br>(1960) | 13.780  | USC+GS MON CONC WK PACIFIC COAST HWY 0.8MI± W OF COAL CANYON (CARBON CANYON) 4FT± N OF NW COR HSE NO 22416 MKD (S-576, 1939)                                     | SY 5387   |
| MALIBU<br>(1960) | 14.926  | CS BR DISC 3FT± N OF N CB PACIFIC COAST HWY @ CATCH BASIN NO A962+00 18FT± E OF SE COR BLDG NO 22775 3FT± W OF E EDGE CATCH BASIN MKD (BM 48-77A, RE 5869, 1960) | SY 5388   |
| MALIBU<br>(1960) | 17.897  | USC+GS MON CONC FLUSH 46FT± S OF S CB PACIFIC COAST HWY @ NW COR OF GATE @ ENT TO MALIBU SPORT FISHING PIER, MALIBU MKD (R-576 1939)                             | SY 5389   |
| MALIBU<br>(1960) | 19.629  | BT SPK PACIFIC COAST HWY + MALIBU CREEK IN CONC BRIDGE S CB 12FT W OF E END OF BRIDGE  | SY 5390   |
| MALIBU<br>(1960) | 19.418  | BT SPK IN PACIFIC COAST HWY + MALIBU CREEK IN CONC BRIDGE S CB 11FT E OF W END OF BRIDGE   | SY 5391   |
| MALIBU<br>(1960) | 22.232  | USC+GS MON PACIFIC COAST HWY @ MALIBU CREEK NW COR BRIDGE NO 53-32 5FT± E OF W END OF BRIDGE TOP OF GUARD RAIL MKD (C-1052, 1960)                                | SY 5392   |
| MALIBU<br>(1960) | 15.292  | CS TRAVERSE MON 5IN BELOW TOP OF CB ON PACIFIC COAST HWY 0.2MI± W OF MALIBU CREEK IN CTR DIVIDING STRIP 3FT± N + 5FT± S OF TAN L+T IN CBS                        | SY 5393   |
| MALIBU<br>(1960) | 15.113  | CSBM BR DISC N E COR PACIFIC COAST HWY @ MALIBU CANYON RD 95FT± N STREET LIGHT NO M3330 73FT± N L+T IN E CB ISLAND 41FT± E L+T E CB MKD (EC COR 5 RD 5869)       | SY 5394   |
| MALIBU<br>(1960) | 56.511  | CS TRAVERSE MON 8IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY ON C/L EC 0.7MI± W MALIBU CREEK 420FT± E MALIBU CANYON RD                                  | SY 5395   |
| MALIBU<br>(1960) | 91.247  | CSBM BR DISC CATCH BASIN CTR DIVIDING STRIP PACIFIC COAST HWY @ MALIBU CANYON RD 75FT± SW TP NO 18600Y + 82FT± SE PP NO 1045723E MKD (BM 83A RE 5869 1960)       | SY 5396   |
| MALIBU<br>(1960) | 171.807 | CS TRAVERSE MON 6IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 1.0MI± W MALIBU CREEK 0.2MI± W MALIBU CANYON RD  | SY 5397   |

| QUAD-YEAR        | ELEV    | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM NUMBER |
|------------------|---------|--|-----------|
| MALIBU<br>(1960) | 197.870 | USC+GS MON 2FT± W OF E END HDWL CULV PACIFIC COAST HWY W OF MALIBU CREEK 55FT± N OF N CB 146FT± W OF E END CTR ISLAND 85FT± E PP NO 1018783E MKD (D-1052 1960)   | SY 5398   |
| MALIBU<br>(1960) | 196.095 | CS TRAVERSE MON 8IN BELOW TOP CB CTR DIVIDING STRIP ON PACIFIC COAST HWY 1.3MI W MALIBU CREEK BTN TAN L+T  | SY 5399   |
| MALIBU<br>(1960) | 175.260 | CS TRAVERSE MON 8IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 1.4MI W MALIBU CREEK   | SY 5400   |
| MALIBU<br>(1960) | 137.558 | CS TRAVERSE MON 8IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 1.8MI± W MALIBU CREEK @ C/L EC BTN TWO L+T   | SY 5401   |
| MALIBU<br>(1960) | 139.924 | CS TRAVERSE MON 10IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 1.8MI W MALIBU CREEK 161FT± W OF EC BTN TWO TAN L+T                                       | SY 5402   |
| MALIBU<br>(1960) | 159.781 | USC+GS MON HDWL 1FT± E OF W END CULV 44FT± N OF N CB CTR DIVIDING STRIP PACIFIC COAST HWY MKD (E 1052 1960)  | SY 5403   |
| MALIBU<br>(1960) | 175.851 | CS TRAVERSE MON 10IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 2.3MI± W MALIBU CREEK 0.1MI± E PUERCO CANYON RD BTN TWO L+T                               | SY 5404   |
| MALIBU<br>(1960) | 160.775 | CS TRAVERSE MON 10IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 350FT± W PUERCO CANYON RD @ C/L E C BTN TWO L+T   | SY 5405   |
| MALIBU<br>(1960) | 134.149 | CS TRAVERSE MON 10IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 0.4MI± E CORRAL CREEK @ C/L BC BTN TWO TAN (X)  | SY 5406   |
| MALIBU<br>(1960) | 38.398  | CS TRAVERSE MON 10IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 0.5MI± W PUERCO CANYON RD 0.1MI± E CORRAL CREEK 134FT± W EC ON C/L PROD BTN TAN L+T IN CB | SY 5407   |
| MALIBU<br>(1960) | 18.630  | CS TRAVERSE MON 10IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 0.6MI± W PUERCO CANYON RD 0.5MI± E SOLSTICE CANYON RD @ BC                                | SY 5408   |
| MALIBU<br>(1960) | 16.884  | CSBM BR CAP FLUSH CONC WK N SIDE PACIFIC COAST HWY + CORRAL CREEK E END CONC BRIDGE NO 53-31 MKD (COUNTY SURVEYOR RE 2177 US 1303-RESET 1938)                    | SY 5409   |
| MALIBU<br>(1960) | 16.882  | USC + GS MON FLUSH CONC WK N SIDE PACIFIC COAST HWY + CORRAL CREEK W END CONC BRIDGE NO 53-31 MKD (F-1052 1960)  | SY 5410   |
| MALIBU<br>(1960) | 18.630  | CS TRAVERSE MON 12IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 450FT± W CORRAL CREEK 0.5MI± E SOLSTICE CANYON @ C/L EC                                   | SY 5411   |
| MALIBU<br>(1960) | 34.207  | CS TRAVERSE MON 12IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 0.2MI± W CORRAL CREEK 0.3MI± E SOLSTICE CANYON RD @ C/L BC                                | SY 5412   |
| MALIBU<br>(1960) | 39.427  | CS TRAVERSE MON 12IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 0.2MI± E SOLSTICE CANYON RD 3.3MI± W CORRAL CREEK   | SY 5413   |
| MALIBU<br>(1960) | 24.949  | L+N 8FT± E OF W END S CONC HDWL PACIFIC COAST HWY @ SOLSTICE CREEK CONC BRIDGE MKD (TBM ELV 24.89)   | SY 5414   |

| QUAD-YEAR        | ELEV    | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM NUMBER |
|------------------|---------|--|-----------|
| MALIBU<br>(1960) | 30.694  | CS TRAVERSE MON IN WELL 10IN BELOW SURFACE<br>1.5FT± S OF S CB + 15FT± E OF W END CTR ISLAND<br>PACIFIC COAST HWY @ SOLSTICE + CORRAL CANYON RD<br>93FT± NE OF NE COR HSE NO 26044 MKD (G-9)                             | SY 5415   |
| MALIBU<br>(1960) | 46.425  | CS TRAVERSE MON FLUSH W/SURFACE 41FT± SW C/L<br>PACIFIC COAST HWY 0.4MI± W SOLSTICE CANYON RD<br>0.3MI± E LATIGO CANYON RD   | SY 5416   |
| MALIBU<br>(1960) | 44.258  | USC+GS MON 1FT ± E OF W END HDWL CULV 35FT± N OF<br>N CB OF ISLAND PACIFIC COAST HWY 0.4MI± W<br>SOLSTICE CANYON RD + 0.3MI± E LATIGO CANYON RD<br>MKD (G-1060 1930 RESET)   | SY 5417   |
| MALIBU<br>(1960) | 91.035  | LA CD TRAVERSE MON IN WELL S SIDE OF PACIFIC<br>COAST HWY 335FT± E OF LATIGO CANYON RD 0.7MI±<br>W OF SOLSTICE CANYON 11FT± E OF SD CULV @ HWY<br>STA (A-723+86)   | SY 5418   |
| MALIBU<br>(1960) | 135.043 | CS TRAVERSE MON FLUSH W/SURFACE 73FT± S C/L<br>PACIFIC COAST HWY 0.2MI± W LATIGO CANYON RD<br>67FT± E FROM END DIVIDING STRIP @ ENT TO (GULLS<br>WAY) HSE NO 26800 1FT± N OF N EDGE OLD HWY                              | SY 5419   |
| MALIBU<br>(1960) | 120.085 | CS TRAVERSE MON FLUSH W/SURFACE S SIDE PACIFIC<br>COAST HWY 0.4MI± W LATIGO CANYON RD<br>46FT± S OF L+T S CB HWY DIVIDING STRIP  | SY 5420   |
| MALIBU<br>(1960) | 77.492  | CS TRAVERSE MON FLUSH W/SURFACE 15FT± S OF S<br>EDGE PVMT PACIFIC COAST HWY 0.5MI± W LATIGO<br>CANYON RD 0.3MI± E ESCONDIDO CREEK<br>37FT± S L+T S CB DIVIDING STRIP   | SY 5421   |
| MALIBU<br>(1960) | 29.250  | CS TRAVERSE MON C/L PROD PACIFIC COAST HWY<br>0.7MI± W LATIGO CANYON RD 372FT± E ESCONDIDO<br>CREEK BRIDGE 46FT± S L+T S CB DIVIDING STRIP   | SY 5422   |
| MALIBU<br>(1960) | 17.359  | CSBM BR CAP FLUSH W/SURFACE PACIFIC COAST HWY<br>+ ESCONDIDO CREEK @ N SIDE ESCONDIDO CREEK<br>BRIDGE @ E END WK 0.8MI± W OF LATIGO CANYON<br>RD 0.5FT± E USC+GS MON MKD (COUNTY SURVEYOR RE<br>2177 US 1307 RESET 1938) | SY 5423   |
| MALIBU<br>(1960) | 17.369  | USC+GS MON FLUSH @ SURFACE PACIFIC COAST HWY<br>+ ESCONDIDO CREEK @ N SIDE ESCONDIDO CREEK<br>BRIDGE @ E END OF WK 0.8MI± W LATIGO CANYON RD<br>0.5MI± W CSBM MON  | SY 5424   |
| MALIBU<br>(1960) | 19.051  | CS TRAVERSE MON 12IN BELOW TOP CB CTR DIVIDING<br>STRIP PACIFIC COAST HWY 150FT± W ESCONDIDO CREEK<br>BRIDGE C/L BC 71FT± W BEG DIVIDING STRIP   | SY 5425   |
| MALIBU<br>(1960) | 85.474  | CS TRAVERSE MON CTR DIVIDING STRIP PACIFIC COAST<br>HWY 0.5MI± W ESCONDIDO CREEK BRIDGE<br>320FT± E EC 1FT± N L+T S CB DIVIDING<br>STRIP   | SY 5426   |
| MALIBU<br>(1960) | 103.634 | CS TRAVERSE MON 12IN BELOW TOP CB CTR DIVIDING<br>STRIP PACIFIC COAST HWY 0.4MI± W ESCONDIDO CREEK<br>BRIDGE 5FT± W BC 37FT± W BEG DIVIDING STRIP  | SY 5427   |
| MALIBU<br>(1960) | 134.220 | CS TRAVERSE MON 12IN BELOW TOP CB CTR DIVIDING<br>STRIP PACIFIC COAST HWY 0.3MI± E PARADISE COVE<br>448FT± W OF BC 1FT± N L+T S CB   | SY 5428   |
| MALIBU<br>(1960) | 123.356 | CS TRAVERSE MON 12IN BELOW TOP CB CTR DIVIDING<br>STRIP PACIFIC COAST HWY 0.2MI± E PARADISE COVE<br>66FT± W OF E END DIVIDING STRIP 1FT± N L+T S CB  | SY 5429   |

| QUAD-YEAR        | ELEV    | D E S C R I P T I O N<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|---------|---|-----------|
| MALIBU<br>(1960) | 105.698 | CS TRAVERSE MON 12IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY NR ENT PARADISE COVE 35FT± E OF W END 1FT± N L+T S CB  | SY 5430   |
| MALIBU<br>(1960) | 118.884 | CS TRAVERSE MON 12IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 0.3MI± W PARADISE COVE 0.5MI± E ZUMA FIRE STA 85FT± S FIRE HYDRANT 1FT± S L+T N CB                 | SY 5431   |
| MALIBU<br>(1960) | 115.360 | CS TRAVERSE MON 12IN BELOW TOP CB CTR DIVIDING STRIP PACIFIC COAST HWY 0.5MI± W PARADISE COVE 0.3MI± E ZUMA FIRE STA 47FT± E EC 1FT± S L+T N CB                           | SY 5432   |
| MALIBU<br>(1960) | 130.073 | CS TRAVERSE MON IN WELL 42FT± S C/L PACIFIC COAST HWY W/D ZUMIREZ DR 42FT± NW OF NW COR ZUMA FIRE STA   | SY 5433   |
| MALIBU<br>(1960) | 144.134 | CS TRAVERSE MON CTR DIVIDING STRIP PACIFIC COAST HWY 0.3MI ± W ZUMA FIRE STA @ BC   | SY 5434   |
| MALIBU<br>(1960) | 161.342 | USC+GS MON FLUSH S CB CTR DIVIDING STRIP PACIFIC COAST HWY 1.0MI± E ZUMA CREEK BRIDGE @ ENT MALIB RIVIERA MOTEL (HSE NO 28920) 9FT± W OF E END OF DIVIDING STRIP          | SY 5435   |
| MALIBU<br>(1960) | 196.322 | CS TRAVERSE MON 39FT± NW APPROX C/L PROD PACIFIC COAST HWY 0.5MI± W ZUMA FIRE STA 0.8MI± E ZUMA CREEK BRIDGE 12FT± W PP NO 710906   | SY 5436   |
| MALIBU<br>(1960) | 200.658 | CS TRAVERSE MON CONC FLUSH W/RD 39FT± N L+T N CB PACIFIC COAST HWY 24/FT± E HEATHER CLIFF RD 63FT± NW L+T BC N CB CTR DIVIDING STRIP 44FT± E TP NO 16326Y                 | SY 5437   |
| MALIBU<br>(1960) | 205.882 | USC+GS MON TOP CONC POST 12IN ABOVE SURFACE 59FT± N C/L PACIFIC COAST HWY + HEATHER CLIFF RD W SIDE OF ENT HSE NO 29127 16FT± FROM GP NO 899894E MKD (R-48-1928-RES 1937) | SY 5438   |
| MALIBU<br>(1960) | 174.187 | CS TRAVERSE MON 4IN ABOVE SURFACE 79FT± N APPROX C/L PACIFIC COAST HWY 0.5MI± NE ZUMA CREEK BRIDGE 17FT± S 2FT± W CHAIN LINK FENCE COR                                    | SY 5439   |
| MALIBU<br>(1960) | 29.903  | CSBM BR CAP CONC N SIDE PACIFIC COAST HWY ZUMA CREEK BRIDGE @ E END WK MKD (STA CO SUR RE 2177 US BM 1312 RES 1938)   | SY 5441   |
| MALIBU<br>(1960) | 29.897  | USC+GS MON FLUSH N SIDE PACIFIC COAST HWY @ ZUMA CREEK BRIDGE @ E END WK  | SY 5442   |
| MALIBU<br>(1960) | 21.778  | CS TRAVERSE MON FLUSH 40FT± S C/L PACIFIC COAST HWY 0.4MI± W ZUMA CREEK BRIDGE 138FT± NE OF NE COR COMFORT STA NO 2470  | SY 5443   |
| MALIBU<br>(1960) | 20.145  | CS TRAVERSE MON 6IN BELOW SURFACE 43FT± S APPROX C/L PACIFIC COAST HWY 0.5MI± SW ZUMA CREEK BRIDGE 230FT± E BC 31FT± E PP NO 936655E 2FT± N 2IN IP MARKER                 | SY 5444   |
| MALIBU<br>(1960) | 15.351  | CS TRAVERSE MON IN WELL 37FT± S APPROX C/L PACIFIC COAST HWY 3.7MI± SW ZUMA CREEK BRIDGE 74FT± E LIFEGUARD HDQTRS GARAGE HSE NO 30064                                     | SY 5445   |
| MALIBU<br>(1960) | 15.226  | CS TRAVERSE MON 40FT± S C/L PACIFIC COAST HWY 323FT± W MORNINGVIEW DR 45FT± N OF NW COR ZUMA BEACH REST ROOM NO 2472  | SY 5446   |

| QUAD-YEAR        | ELEV    | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|---------|---|-----------|
| MALIBU<br>(1960) | 14.780  | CS TRAVERSE MON FLUSH W/PVMT 41FT± S C/L<br>PACIFIC COAST HWY 1.1MI± W ZUMA CREEK BRIDGE<br>58FT± W PP NO 817635E   | SY 5447   |
| MALIBU<br>(1960) | 7.474   | CSBM BR CAP IN WELL 18IN BELOW SURFACE 162FT± S<br>C/L PACIFIC COAST HWY 41FT± SE L+T CONC SLAB @<br>SE COR COMFORT STA LA CO BLDG NO 2474 + 65FT±<br>SE L+T CONC SLAB @ SW COR SAME BLDG MKD (Z 4B<br>RE 329)                        | SY 5448   |
| MALIBU<br>(1960) | 15.768  | CS TRAVERSE MON FLUSH W/PVMT 40FT± S C/L PACIFIC<br>COAST HWY 0.4MI± E BRIDGE @ TRANCAS CYN<br>19FT± W PP NO 817620E  | SY 5449   |
| MALIBU<br>(1960) | 13.271  | CS TRAVERSE MON FLOSH W/PVMT 39FT± S C/L PACIFIC<br>COAST HWY 275FT± E BRIDGE @ TRANCAS CYN<br>25FT± E PP NO 817619E  | SY 5450   |
| MALIBU<br>(1960) | 18.616  | BRONZE TABLET S SIDE PACIFIC COAST HWY @ TRANCAS<br>CREEK BRIDGE @ W END WK MKD (R-49 1928 RESET<br>1938)   | SY 5451   |
| MALIBU<br>(1960) | 14.031  | CSBM MON 12IN BELOW SURFACE NR INT PACIFIC<br>COAST HWY + TRANCAS CYN RD S SIDE BROAD BEACH RD<br>@ W END ZUMA BEACH 2FT± N BARBED WIRE FENCE +<br>2IN IP MARKER 44FT± W TP NO 15504Y MKD<br>(RM Z-5 RE 329)                          | SY 5452   |
| MALIBU<br>(1960) | 7.126   | CSBM MON 24IN BELOW SURFACE W OF TRANCAS CREEK<br>@ W END ZUMA BEACH 2FT± N 2IN IP ON LINE WITH<br>BT SPK + WASHER BY ENT (TRANCAS COUNTRY STORE)<br>MKD (Z-5 RE 329)   | SY 5453   |
| MALIBU<br>(1960) | 73.197  | CS TRAVERSE MON FLUSH W/SURFACE PACIFIC COAST<br>HWY 0.8MI± W TRANCAS CYN BRIDGE 92FT± E BC<br>41FT± N L+T N CB OF DIVIDING STRIP   | SY 5454   |
| MALIBU<br>(1960) | 71.839  | CS TRAVERSE MON IN WELL 36FT± N APPROX C/L<br>PACIFIC COAST HWY 0.7MI± W BRIDGE @ TRANCAS CYN<br>250FT± W LUNITA RD 30FT± E TP NO 16033Y  | SY 5455   |
| MALIBU<br>(1960) | 74.463  | CS TRAVERSE MON 5IN BELOW SURFACE 37FT± N APPROX<br>C/L PACIFIC COAST HWY 0.8MI± W TRANCAS CREEK<br>685FT± W LUNITA RD 44FT± W OF TP NO 25836Y  | SY 5456   |
| MALIBU<br>(1960) | 102.996 | USC+GS MON FLUSH W/N CB DIVIDER STRIP PACIFIC<br>COAST HWY 1.2MI± W HWY BRIDGE OF TRANCAS CREEK<br>153FT± N FROM NW COR MALIBU WATER CO SHED<br>HOUSING (ENCINAL BOOSTER) @ E END GREEN<br>CYLINDRICAL TANK 55FT± S FROM TP NO 25848Y | SY 5457   |
| MALIBU<br>(1960) | 104.891 | CS TRAVERSE MON PACIFIC COAST HWY 1.2MI± W<br>BRIDGE @ TRANCAS CYN 45FT± S L+T S CB DIVIDING<br>STRIP 2FT± NE 2IN IP  | SY 5458   |
| MALIBU<br>(1960) | 118.730 | CS TRAVERSE MON 15IN BELOW TOP CB CTR DIVIDING<br>STRIP PACIFIC COAST HWY 1.4MI± W BRIDGE @<br>TRANCAS CYN 42FT± S PP NO 26014Y   | SY 5459   |
| MALIBU<br>(1960) | 88.277  | CS TRAVERSE MON 6IN BELOW SURFACE 37FT± N APPROX<br>C/L PACIFIC COAST HWY 1.5MI± E DECKER RD 220FT±<br>W BROAD BEACH RD   | SY 5460   |
| MALIBU<br>(1960) | 123.363 | CS TRAVERSE MON 18IN BELOW SURFACE 41FT± N<br>APPROX C/L PACIFIC COAST HWY 1.3MI± E DECKER<br>RD 140FT± E DRWY HSE NO 32001   | SY 5461   |
| MALIBU<br>(1960) | 168.891 | CS TRAVERSE MON IN WELL 14IN BELOW SURFACE 39FT±<br>S C/L PACIFIC COAST HWY NR HSE NO 32216 +<br>32232 0.5± W OF P/L FENCE PROD BETWEEN HSES<br>11FT± N PP NO 1059757E  | SY 5462   |

| QUAD-YEAR        | ELEV    | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM NUMBER |
|------------------|---------|--|-----------|
| MALIBU<br>(1960) | 164.029 | CS TRAVERSE MON 1FT# ABOVE EDGE RD 42FT# N C/L PACIFIC COAST HWY 25FT# W CATCH BASIN 2FT# S 2IN IP MARKER MKD (DUME POINT C-8 RESET 1957 RE 5869)  | SY 5463   |
| MALIBU<br>(1960) | 178.970 | CS TRAVERSE MON IN WELL 9IN BELOW SURFACE 39FT# S C/L PACIFIC COAST HWY 0.6MI# E DECKER RD 53FT# E CTR DRWY HSE NO 32606 11FT# N PP NO 1059771E MKD (DUME POINT B-8 RESET 1955)  | SY 5464   |
| MALIBU<br>(1960) | 97.057  | USGS DISC TOP CONC POST 12IN ABOVE SURFACE 87FT# S APPROX C/L PACIFIC COAST HWY 320FT# W DECKER RD 68FT# SW TP NO 1090481E MKD (R-50 1928)   | SY 5465   |
| MALIBU<br>(1960) | 130.232 | CS TRAVERSE MON IN WELL 9IN BELOW SURFACE 36FT# S C/L PACIFIC COAST HWY 0.9MI# W DECKER RD 37FT# NW PP NO 1085709E MKD (ARROYO SEQUIT L-7A RESET 1955)   | SY 5466   |
| MALIBU<br>(1960) | 126.025 | CS TRAVERSE MON IN WELL 39FT# S C/L PACIFIC COAST HWY 0.5MI# W DECKER RD 12FT# NE PP NO 1059900E 72FT# E OF E END STEEL GUARDRAIL S EDGE PVMT MKD (ARROYO SEQUIT L-8B RESET 1957 RE 5869)  | SY 5467   |
| MALIBU<br>(1960) | 154.460 | CS TRAVERSE MON IN WELL 9IN BELOW SURFACE 39FT# N C/L PACIFIC COAST HWY 1.5MI# W DECKER RD 65FT# E SE COR CATCH BASIN MKD (ARROYO SEQUIT K-7A RESET 1955)  | SY 5468   |
| MALIBU<br>(1960) | 149.747 | CS TRAVERSE MON 8IN ABOVE SURFACE IN FACE ASPHALT CB 42FT# N APPROX C/L PACIFIC COAST HWY 19FT# W SW COR CATCH BASIN CULV MKD @ARROYO SEQUIT J-7 RESET 1955)   | SY 5469   |
| MALIBU<br>(1960) | 30.962  | CSBM MON FLUSH W/SURFACE 86FT# S C/L PACIFIC COAST HWY 500FT# E ARROYO SEQUIT 35FT# S PP NO 1090612E MKD (RM Z-26)   | SY 5470   |
| MALIBU<br>(1960) | 15.500  | CSBM MON 4IN BELOW SURFACE 156FT# S C/L PACIFIC COAST HWY 500FT# E ARROYO SEQUIT 163FT# SE PP NO 1090613E 104FT# S OF PP NO 1090612E MKD (Z-26)  | SY 5471   |
| MALIBU<br>(1960) | 18.318  | USC+GS MON IN WK FLUSH W/SURFACE S SIDE PACIFIC COAST HWY @ ARROYO SEQUIT 17FT# E OF W END OF BRIDGE MKD (Q-583 RESET 1954)  | SY 5472   |
| MALIBU<br>(1960) | 35.104  | CSBM MON 6IN ABOVE SURFACE TOP SLOPE 475FT# S PACIFIC COAST HWY 0.2MI# W ARROYO SEQUIT BRIDGE 26FT# W LIFE GUARD STATION MKD (SEQUIT RM 2 1948)  | SY 5473   |
| MALIBU<br>(1960) | 22.748  | USC+GS TRIANGULATION DISC FLUSH 525FT# S C/L PACIFIC COAST HWY 0.2MI# W ARROYO SEQUIT BRIDGE 25FT# FROM EDGE CLIFF ON A ROCK POINT MKD (SEQUIT 1927)   | SY 5474   |
| MALIBU<br>(1960) | 48.496  | CSBM BR CAP TOP 15IN CONC POST 2IN ABOVE SURFACE 44FT# S C/L PACIFIC COAST HWY 0.1MI# W ARROYO SEQUIT BRIDGE 3FT# S OF S EDGE PVMT 24FT# E PP NO1090621E 35FT# NE DEADMAN 175FT# NE OF NE COR CHECKING STA FOR LEO CARRILO STATE BEACH MKD (ARROYO SEQUIT H-7A RESET 1957 RE 5869) | SY 5475   |
| MALIBU<br>(1960) | 86.965  | CSBM BR CAP CONC POST 6IN ABOVE SURFACE 62FT# S C/L PACIFIC COAST HWY LA CO-VENTURA CO LINE 12FT# S REDWOOD FENCE MKD (VENTURA CO LINE LA CO LINE)   | SY 5476   |

| QUAD-YEAR        | ELEV    | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|---------|---|-----------|
| MALIBU<br>(1960) | 75.227  | USC+GS MON 52FT± N C/L PACIFIC COAST HWY 0.1MI± E LA CO - VENTURA CO LINE 1FT± E OF W END HDWL CULV MKD (U-1051 1960)   | SY 5477   |
| MALIBU<br>(1960) | 86.793  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 26FT± W OF W EDGE MAC MULHOLLAND HWY 0.5MI± N PACIFIC COAST HWY + 4FT± E 4-STRAND BARBED WIRE FENCE MKD (BM 58-1 RE 5869 1961)   | SY 5478   |
| MALIBU<br>(1960) | 191.475 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 29FT± W OF W EDGE MAC MULHOLLAND HWY 0.8MI± N PACIFIC COAST HWY 66FT± SW OF S POST OF STEEL GUARD RAIL + 134FT± SW OF L+CE TAG IN A CONC + ROCK DRAIN MKD (BM 58-2 RE 5869 1961)   | SY 5479   |
| MALIBU<br>(1960) | 307.781 | CSBM FLUSH W/SURFACE 6FT± E OF E EDGE MAC MULHOLLAND HWY 1.2MI± NE PACIFIC COAST HWY ON CREST OF HILL @ FOOT SMALL BLUFF MKD (CB-11 RE 63)  | SY 5480   |
| MALIBU<br>(1960) | 226.843 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 18FT± E OF E EDGE MAC MULHOLLAND HWY 1.5MI± N PACIFIC COAST HWY IN VALLEY @ CULV NO B-783 64FT± SW N POST OF STEEL GUARD RAIL 54FT± E HWY STA MARKER 83+06 + 73FT± NE L+CE TAG W HDWL CULV NO B-783 MKD (BM 58-3 RE 5869 1961)             | SY 5481   |
| MALIBU<br>(1960) | 399.137 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE IN CUT BANK 32FT± E APPROX C/L MULHOLLAND HWY 2 1MI± N PACIFIC COAST HWY 0.5MI± N CULV NO B-783 MKD (BM 58-4 RE 5869 1961)   | SY 5482   |
| MALIBU<br>(1960) | 444.247 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 28FT± S APPROX C/L MULHOLLAND HWY 2.3MI± N PACIFIC COAST HWY @ CREST OF HILL 11FT± W 5IN OAK TREE MKD (BM 58-5 RE 5869 1961)   | SY 5483   |
| MALIBU<br>(1960) | 412.855 | CS BM FLUSH W/SURFACE 42FT± E APPROX C/L MULHOLLAND HWY 2.5MI± N PACIFIC COAST HWY S SIDE DRAW IN CUT BANK 52FT± E HWY STA MARKER 131+15 + 47FT± SE S POST OF A STEEL GUARD RAIL MKD (CB-17 RE 63)  | SY 5484   |
| MALIBU<br>(1960) | 412.451 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 21FT± E APPROX C/L MULHOLLAND HWY @ ROAD TO CAMP BLOOMFIELD (FOUNDATION FOR THE JUNIOR BLIND) 2.6MI± N PACIFIC COAST HWY 45FT± NE PP NO1269265E 64FT± S HWY STA MARKER 145+51 + 4FT± NE FIRE TELEPHONE NO 72-10 MKD (BM 58-6 RE 5869 1961) | SY 5485   |
| MALIBU<br>(1960) | 408.193 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 21FT± E APPROX C/L MULHOLLAND HWY 3.1MI± N PACIFIC COAST HWY @ W + E FORKS OF ARROYO SEQUIT 4FT± NE PP NO 1269251E S PP NO 1225900E + 184FT± S SE COR CULV NO B-1100 MKD (BM 58-7 RE 5869 1961)  | SY 5486   |
| MALIBU<br>(1960) | 512.801 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 24FT± E APPROX C/L MULHOLLAND HWY 3.4MI± N PACIFIC COAST HWY 59FT± S PP NO 1225888E 75FT± SE GUY POLE NO 1225889E + 132FT± N PP NO 1225890E MKD (BM 58-8 RE 589 1961)  | SY 5487   |
| MALIBU<br>(1960) | 577.848 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 35FT± N APPROX C/L MULHOLLAND HWY 20FT± SW APPROX C/L DIRT RD TO WILLOW CREEK RANCH 3.6MI± N PACIFIC COAST HWY 60FT± W HWY STA MARKER 196+07 MKD (BM 58-9 RE 5869 1961)  | SY 5488   |



| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 711.178  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 23FT± SY<br>E APPROX C/L MULHOLLAND HWY 4.0MI±N PACIFIC<br>COAST HWY 3 4MI± W DECKER RD SW HSE NO 35100<br>MULHOLLAND HWY + 4FT± NE PP NO 1225878E MKD<br>(BM 58-10 RE 5869 1961)  | 5489      |
| MALIBU<br>(1960) | 783.882  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 38FT± SY<br>W APPROX C/L MULHOLLAND HWY @ DIRT RD TO CONC<br>WATER TOWER NO 3798 ( FIRE TANK TRUCK FILLING<br>POINT ) 3.2MI± W DECKER RD + 15FT± S TANK<br>FILLING BOX MKD (BM 58-11 RE 5369 1961)   | 5490      |
| MALIBU<br>(1960) | 800.612  | L+BT SPK 63FT± W APPROX C/L MULHOLLAND HWY A<br>DIRT RD TO CONC WATER TANK NO 3798 (FIRE TANK<br>TRUCK FILLING POINT) 3.2MI± W DECKER RD IN S EDG<br>CONC WATER TANK 3FT± W SE COR  | SY 5491   |
| MALIBU<br>(1960) | 882.999  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>65FT± SW APPROX C/L MULHOLLAND HWY 2.8MI± W<br>DECKER RD 151FT± SW HWY STA MARKER 243+56<br>E SIDE HWY @ A DRAW 131FT± NW OF N<br>POST OF STEEL GUARD RAIL + 3FT± E OF E<br>FACE 4FT HIGH BLACK TRIANGULAR ROCK MKD<br>(BM 58-12 RE 5869 1961)                                      | SY 5492   |
| MALIBU<br>(1960) | 1038.103 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>23FT± SE APPROX C/L MULHOLLAND HWY + DIRT RD<br>TO WAKONDA (BEVERLY HILLS YMCA CAMP) HSE NO<br>34342 3FT NE PP NO 1209981E 4FT± E SIGN MKD<br>(WAKONDA BEVERLY HILLS YMCA CAMP) 247FT± SW<br>HWY STA MARKER 272+91 + 234FT± NE HWY STA MARKER<br>268+10 MKD (BM 58-13 RE 5869 1961) | SY 5493   |
| MALIBU<br>(1960) | 1096.433 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>27FT± E APPROX C/L MULHOLLAND HWY 1.8MI± W<br>DECKER RD S DIRT RD HSE NO 34135 N DIRT RD TO<br>HSE NO 34138 342FT S HWY STA MARKER 300+24<br>36FT± NE 12IN PINE TREE + 7FT± N FIRE TP<br>NO 72-5 MKD (BM 58-14 RE 5869 1961)  | SY 5494   |
| MALIBU<br>(1960) | 1234.325 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>26FT± N APPROX C/L MULHOLLAND HWY 1.4MI± W<br>DECKER RD 137FT± NW HWY STA MARKER 320P60 52FT±<br>NE HWY STA MARKER 318+96 MKD (BM 58-15 RE<br>5869)   | SY 5495   |
| MALIBU<br>(1960) | 1351.099 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>20FT± E APPROX C/L MULHOLLAND HWY 1.1MI±W<br>DECKER RD 30FT± SE OF HWY STA MARKER 337+72<br>+ 42FT± NE OF SE COR E WALL ROCK CULV MKD<br>(BM 58-16 RE 5869 1961)  | SY 5496   |
| MALIBU<br>(1960) | 1475.449 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>24FT± S APPROX C/L MULHOLLAND HWY 0.6MI± W<br>DECKER RD 4FT± S PP NO 658020H + 28FT± W FIRE<br>TP NO LC 1396 FD MKD (BM 58-17 RE 5869 1961)   | SY 5497   |
| MALIBU<br>(1960) | 1548.132 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>24FT± S APPROX C/L MULHOLLAND HWY @ LITTLE<br>SYCAMORE CYN RD 0.4MI± W DECKER RD 9FT± S<br>6IN OAK TREE 180FT± SE HWY STA MARKER 370+45<br>44FT± E PP NO 1143747E MKD (BM 58-18 RE<br>5869 1961)  | SY 5498   |
| MALIBU<br>(1960) | 1504.832 | USGS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>264FT± S APPROX C/L MULHOLLAND HWY + 24FT± W<br>OF W EDGE DECKER RD 129FT± SW PP NO 798266E<br>111FT± NW HWY STA MARKER A-4.96 MKD (R-53 1928)  | SY 5499   |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 1595.160 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>13FT± E OF E EDGE MAC DECKER RD 0.3MI± N<br>MULHOLLAND HWY NR HSE NO 33335 11FT± SE FIRE<br>TP NO LC 1331 FD 56FT± SE COR 4 STRAND BARB<br>WIRE FENCE + 104FT± SE PP NO 664578E MKD<br>(BM 58-19 1961)                                    | SY 5500   |
| MALIBU<br>(1960) | 1733.824 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>13FT± S OF S EDGE MAC DECKER RD 0.9MI± N<br>MULHOLLAND HWY @ DRWY HSE NO 33182 1FT± NE<br>14IN GUM TREE + 14FT± W 5IN PINE TREE MKD<br>(BM 58-20 RE 5869 1961)  | SY 5501   |
| MALIBU<br>(1960) | 1788.738 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>19FT± SW OF S EDGE MAC DECKER RD @ A TURNOUT<br>0.6MI± S MULHOLLAND HWY 11FT± NW OAK TREE<br>+ 10FT± NE 10IN ACACIA TREE MKD (BM 58-21 RE<br>5869 1961)   | SY 5502   |
| MALIBU<br>(1960) | 1817.544 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>54FT± N APPROX C/L MULHOLLAND HWY 110FT± NE<br>DECKER RD 114FT± NE PP NO 664560E + 122FT± SE<br>12FT DIAMETER STREET WATER TANK MKD (BM 58-22<br>RE 5869 1961)  | SY 5503   |
| MALIBU<br>(1960) | 1868.051 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>19FTS8 S APPROX C/L MULHOLLAND HWY 0.5MI± E<br>DECKER RD 140FT± E CREST OF HILL 3FT± S FIRE<br>TP NO LC 1063 FD 140FT± SW HWY STA MARKER 25+93<br>+ 79FT± SE PP NO 664553E MKD (BM 58-23 RE 5869<br>1961)                                 | SY 5504   |
| MALIBU<br>(1960) | 1911.297 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>38FT± W APPROX C/L MULHOLLAND HWY 0.8MI± E<br>DECKER RD 82FT± NW HWY STA MARKER 47+73 + 120FT±<br>SW FIRE TP NO LC 1044 FD MKD (BM 58-24 RE 5869<br>1961)   | SY 5505   |
| MALIBU<br>(1960) | 2011.994 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 25FT±<br>S APPROX C/L MULHOLLAND HWY 1.1MI± E DECKER RD<br>W SIDE DRAW 6FT± S PP NO 1095652E 164FT± E CREST<br>OF HILL + 82FT± SW HWY STA MARKER 64+99 MKD<br>(BM 58-25 RE 5869 1961)  | SY 5506   |
| MALIBU<br>(1960) | 1952.050 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>20FT± N APPROX C/L MULHOLLAND HWY 1.6MI± E<br>DECKER RD 7FT± SE FIRE TP NO LC 1000 FD +<br>115FT± W FIRE TP NO LC 999 FD MKD (BM 58-26<br>RE 5869 1961)   | SY 5507   |
| MALIBU<br>(1960) | 1931.128 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>24FT± NE APPROX C/L MULHOLLAND HWY 2.0MI± E<br>DECKER RD 1.3 MI± W BACKUS RD 94FT± E HWY STA<br>MARKER 100+74 23FT± S FIRE TP NO LC 981 FD +<br>119FT± NW FIRE TP NO LC 980 FD MKD (BM 58-27<br>RE 5869 1961)                             | SY 5508   |
| MALIBU<br>(1960) | 1920.125 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>22FT± N APPROX C/L MULHOLLAND HWY @ ENCINAL<br>CANYON RD E 1.0MI± W BACKUS RD 69FT± NE FIRE<br>TP NO LC 968 FD 75FT± W FIRE TP NO LC 967 FD +<br>19FT± SW W GATE POST 3FT GATE IN 6-STRAND BARB<br>WIRE FENCE MKD (BM 58-28 RE 5869 1961) | SY 5509   |
| MALIBU<br>(1960) | 1838.597 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>27FT± NE APPROX C/L MULHOLLAND HWY 0.7MI± W<br>BACKUS RD 7FT± NE FIRE TP NO LC 958 FD 3FT± S<br>6-STRAND BARB WIRE FENCE + 90FT± NW PP NO<br>828729E MKD (BM 58-29 RE 5869 1961)  | SY 5510   |

| QUAD-YEAR        | ELEV     | D E S C R I P T I O N<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 1721.878 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>31FT# SE APPROX C/L MULHOLLAND HWY 0.4MI# W<br>BACKUS RD 86FT# SE FIRE TP NO LC 945 FD 81FT#<br>SW FIRE TP NO LC 944 FD + 156FT# SW OF SW COR<br>POST 4-STRAND BARB WIRE FENCE MKD (BM 58-30<br>RE 5869 1961)   | SY 5511   |
| MALIBU<br>(1960) | 1704.340 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>34FT# S APPROX C/L MULHOLLAND HWY 40FT# W<br>APPROX C/L BACKUS RD 109FT# SW HWY STA MARKER<br>0+65 73FT# SW FIRE TP 72-14 + 85FT# SW PP NO<br>987732 E MKD (BM 58-31 RE 5869 1961)  | SY 5512   |
| MALIBU<br>(1960) | 1777.573 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>25FT# S APPROX C/L MULHOLLAND HWY 0.4MI# E<br>BACKUS RD @ CREST HILL 5FT# S MAIL-BOX HSE<br>NO 31302 2FT# N 3-STRAND BARB WIRE FENCE 62FT#<br>S PP NO 616946H 87FT# SE TANK TRUCK FILLING<br>POINT + 32FT# NE 24IN PINE TREE MKD (BM 58-32<br>RE 5869 1961) | SY 5513   |
| MALIBU<br>(1960) | 1688.234 | CS BR CAP IN RED ROCK ON HILL 2FT# ABOVE ROAD<br>15FT# W APPROX C/L MULHOLLAND HWY 0.7MI# E<br>BACKUS RD 121FT# SW 12IN CORRUGATED IP DRAIN<br>+ 2FT# N 2IN IP MARKER MKD (BM 58-33 RE 5869<br>1961)  | SY 5514   |
| MALIBU<br>(1960) | 1576.557 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE ON<br>HILL 25FT# SW APPROX C/L MULHOLLAND HWY 1.0MI#<br>E BACKUS RD 53FT# SE OF SE COR ROCK RUBBLE DRAIN<br>+ 31FT# SE HWY STA MARKER 50+70 MKD (BM 58-34<br>RE 5869 1961)   | SY 5515   |
| MALIBU<br>(1960) | 1440.781 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE ON<br>HILL 43FT# E APPROX C/L MULHOLLAND HWY 1.3MI#<br>E BACKUS RD 59FT# E OF 3/4IN IP CONC PLUG + CE<br>TAG SET FLUSH IN S BERM OF MAC DRAIN + 83FT#<br>NW PP MKD (BM 58-35 RE 5869 1961)   | SY 5516   |
| MALIBU<br>(1960) | 1351.212 | CS BR CAP IN ROCK 3FT# ABOVE RD ON HILL 14FT#<br>E APPROX C/L MULHOLLAND HWY 1.5MI# E BACKUS RD<br>58FT# SE PP NO 899988E 44FT# NE 12IN PINE TREE<br>+ 79FT# NE 14IN PINE TREE MKD (BM 58-36 RE<br>5869 1961)   | SY 5517   |
| MALIBU<br>(1960) | 1259.125 | CS BR CAP TOP OF 8FT X 10FT X 6FT SANDSTONE<br>ROCK 5FT# ABOVE RD ON HILL 15FT# NW APPROX C/L<br>MULHOLLAND HWY 1.0MI# W SEMINOLE HOT SPRINGS<br>34FT# SW OF SW END 12IN CORRUG IP DRAIN +<br>27FT# NE PP NO 899934E MKD (BM 58-37 RE 5869<br>1961)   | SY 5518   |
| MALIBU<br>(1960) | 1175.854 | CS BR CAP ROCK 2FT# ABOVE RD ON HILL 15FT# NE<br>APPROX C/L MULHOLLAND HWY 0.8MI# W SEMINOLE HOT<br>SPRINGS 128FT# NW HWY STA MARKER 102+21 + 114FT#<br>SE SIGN (SEMINOLE 1MI) ON A LARGE SAND STONE<br>ROCK MKD (BM 58-38 RE 5869 1961)  | SY 5519   |
| MALIBU<br>(1960) | 1050.801 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>26FT# NW APPROX C/L MULHOLLAND HWY ON HAIRPIN<br>CURVE 30FT# SW DEADMAN 28FT# S PP NO 689138E<br>118FT# NE OF NE COR + 129FT# NE OF NW COR<br>FOUNDATION OF BURNED OUT HSE MKD (BM 58-39 RE<br>5869 1961)   | SY 5520   |
| MALIBU<br>(1960) | 966.768  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>31FT# SW APPROX C/L MULHOLLAND HWY 0.3MI# W<br>SEMINOLE HOT SPRINGS 105FT# SW HWY STA MARKER<br>138+86 66FT# S 12IN PINE TREE + 8FT# SW<br>PP NO 1308510E MKD (BM 58-40 RE 5869 1961)   | SY 5521   |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 872.311  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>29FT± SE APPROX C/L MULHOLLAND HWY 0.1MI± E<br>SEMINOLE HOT SPRINGS W SIDE DIRT ROAD 69FT± SE<br>16IN PINE TREE 76FT± SW 14IN PINE TREE 115FT±<br>SW 18IN PINE TREE + 112FT± SW HWY STA MARKER<br>153+45 MKD (BM 58-41 RE 5869 1961)  | SY 5522   |
| MALIBU<br>(1960) | 839.062  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>34FT± N APPROX C/L MULHOLLAND HWY + 45FT± E<br>OF E EDGE MAC SIERRA CREEK RD 76FT± NE PP<br>NO 609660H + 176FT± NW PP NO 609659H MKD<br>(BM 58-42 RE 5869 1961)   | SY 5523   |
| MALIBU<br>(1960) | 762.913  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>36FT± N APPROX C/L MULHOLLAND HWY 0.3MI± W<br>LAKE VISTA DR 278FT± NE DRWY R D YARD NO 8<br>9FT± N PP NO 543183H 24FT± S OF A DEADMAN<br>+ 32FT± NE OF HWY STA MARKER 221+73 MKD<br>(BM 58-44 RE 5869 1961)                           | SY 5524   |
| MALIBU<br>(1960) | 774.774  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>51FT± S APPROX C/L MULHOLLAND HWY 19FT± SW<br>APPROX C/L LAKE VISTA DR 5FT± SE 18IN OAK TREE<br>12FT± NW 20IN OAK TREE + 109FT± SE PP NO 535950H<br>MKD (BM 58-45 RE 5869 1961)   | SY 5525   |
| MALIBU<br>(1960) | 849.737  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>33FT± S APPROX C/L MULHOLLAND HWY 0.5MI± E<br>LAKE VISTA DR 154FT± W PP NO 488512H 115FT± E<br>PP NO 488513H + 127FT± SE GUY POLE NO 488514H<br>MKD (BM 58-46 RE 5869 1961)   | SY 5526   |
| MALIBU<br>(1960) | 760.640  | CS BR CAP CTR 4FT CONC WK FLUSH MULHOLLAND HWY<br>@ S SIDE BRIDGE NO B 1092 OVER MALIBU LAKE 1FT±<br>W OF E END BRIDGE MKD (BM 58-47 RE 5869 1961)  | SY 5527   |
| MALIBU<br>(1960) | 838.079  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>62FT± S APPROX C/L MULHOLLAND HWY + 39FT± E<br>APPROX C/L CORNELL RD 9FT± SE PP NO 1045755E<br>8FT± S DEADMAN 10FT± N OF W COR OF 3.5FT BOARD<br>RAIL FENCE + 33FT± SW E COR BOARD RAIL FENCE<br>MKD (BM 58-48 RE 5869 1961)          | SY 5528   |
| MALIBU<br>(1960) | 924.377  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>26FT± N APPROX C/L MULHOLLAND HWY + 0.5MI± E<br>CORNELL RD 57FT± NE PP NO 843978E + 12FT±<br>NE PP NO 843978E MKD (BM 58-49 RE 5869 1961)   | SY 5529   |
| MALIBU<br>(1960) | 946.135  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>24FT± N APPROX C/L MULHOLLAND HWY 1.1MI± E<br>CORNELL RD E SIDE DRAW 5FT± NE ROCK DRAIN<br>101FT± NE PP NO 843969E 182FT± E HWY STA MARKER<br>385+09 + 30FT± NW LA CO FIRE DEPT TP MKD<br>(BM 58-50 RE 5869 1961)                     | SY 5530   |
| MALIBU<br>(1960) | 1020.657 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>27FT± SE APPROX C/L MULHOLLAND HWY 1.5MI± E<br>CORNELL RD 139FT± SE PP NO 843963E 34FT± NE<br>FIRE TANK TRUCK FILLING POINT 48FT± SW 4IN<br>DIA 3FT HIGH PIPE PAINTED YELLOW + 126FT± SW<br>PP NO 843962E MKD (BM 58-51 RE 5869 1961) | SY 5531   |
| MALIBU<br>(1960) | 979.460  | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>42FT± S APPROX C/L MULHOLLAND HWY 1.7MI± E<br>CORNELL RD IN CUT 103FT± SW PP NO 843958E +<br>178FT± SE PP NO 843959E MKD (BM 58-52 RE 5869<br>1961)   | SY 5532   |

| QUAD-YEAR        | ELEV    | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM NUMBER |
|------------------|---------|--|-----------|
| MALIBU<br>(1960) | 908.318 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 24FT# SE APPROX C/L MULHOLLAND HWY 1.3MI# W LAS VIRGENES RD 51FT# E PP NO 843954E + 196FT# SW PP NO 843953E MKD (BM 58-53 RE 5869 1961)   | SY 5533   |
| MALIBU<br>(1960) | 824.370 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 23FT# NW APPROX C/L MULHOLLAND HWY 1.0MI# W LAS VIRGENES RD E SIDE DRAW 11FT# NW HWY STA MARKER 452+27 129FT#NW PP NO 718781E 147FT# NE PP NO 718782E + 141FT#NW LA CO FIRE DEPT TP MKD (BM 58-54 RE 5869 1961) | SY 5534   |
| MALIBU<br>(1960) | 758.004 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 23FT# NE APPROX C/L MULHOLLAND HWY 0.9MI# W LAS VIRGENES RD 224FT# SE HWY STA MARKER 465+57 89FT# S COR BARB WIRE + ELECTRIC FENCE + 38FT# SW 40IN DAK TREE MKD (BM 58-55 RE 5869 1961)                         | SY 5535   |
| MALIBU<br>(1960) | 658.727 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE 31FT# NE APPROX C/L MULHOLLAND HWY 0.5MI# W LAS VIRGENES RD 3FT# SW 3-STRAND BARB WIRE FENCE 74FT# N PP NO 718777E + 436FT# NW OF HWY STA MARKER 484+78 MKD (BM 58-56 RE 5869 1961)                             | SY 5536   |
| MALIBU<br>(1960) | 573.986 | CS BR CAP 2FT# S OF N EDGE S CONC WK @ MULHOLLAND HWY + LAS VIRGENES CREEK SW COR OF CONC BRIDGE NO B 833 1FT# E OF W END OF BRIDGE MKD (BM 58-57 RE 5869 1961)  | SY 5537   |
| MALIBU<br>(1960) | 39.196  | LACE BR CAP MON IN WELL 10IN BELOW SURFACE ON S SIDE PACIFIC COAST HWY @ TOPANGA CYN BLVD OPP HSE NO 18618 PACIFIC COAST HWY + 56FT# W SPK + TIN TP NO 1378Y MKD (BEACH SURVEY CONTROL LINE N-71)  | SY 5538   |
| MALIBU<br>(1960) | 80.530  | FC CONC MON FLUSH W/GROUND @ TOPANGA CYN BLVD + BROOKSIDE DR 0.5MI#N PACIFIC COAST HWY 11FT# E OF E EDGE PVMT TOPANGA CYN BLVD 53FT#E 14IN GUM TREE + 57FT# E 24IN GUM TREE MKD (FC BM 117-F-1-1946)   | SY 5539   |
| MALIBU<br>(1960) | 153.587 | CS BR CAP BM 12IN POST 4IN ABOVE SURFACE TOPANGA CYN BLVD 1.1MI# N PACIFIC COAST HWY 19FT# E C/L TOPANGA CYN BLVD 2FT# W PP NO 689117E 45FT# E MAIL BOX NO 2935 TOPANGA CYN BLVD + 175FT# S CULV + MILEAGE MARKER @A-1.25MI) MKD (BM 56-2 RE 5869 1960)    | SY 5540   |
| MALIBU<br>(1960) | 221.528 | FC BR CAP CONC SIDE CLIFF TOPANGA CYN BLVD 1.6MI# N PACIFIC COAST HWY 9FT# E OF E SIDE PVMT 43FT# S PP NO 775272E 61FT# SE GUY POLE NO 12543Y + 78FT# N 18IN CORRUGATED IP CULV W/MILEAGE MARKER (A-1 575MI) MKD (FC BM 117-F3 1946)                       | SY 5541   |
| MALIBU<br>(1960) | 296.680 | FC BR CAP TOPANGA CYN BLVD + TOPANGA CREEK 2.0MI# N PACIFIC COAST HWY 18FT# W C/L TOPANGA CYN BLVD NW COR BRIDGE NO 53-143 89FT# S PP  | SY 5542   |
| MALIBU<br>(1960) | 593.249 | ST HWY BR CAP 8IN BELOW SURFACE TOPANGA CYN BLVD 2.7MI# N PACIFIC COAST HWY 15FT# E OF E EDGE PVMT 79FT# N PP NO 751030E 27FT# S PP NO 751032E + 27FT# SW PP NO 751031E MKD (DIVISION HIGHWAY)   | SY 5543   |
| MALIBU<br>(1960) | 736.690 | CS BR CAP BM 12IN CONC POST 6IN ABOVE SURFACE TOPANGA CYN BLVD @ DRWY (FITZGERALDS) 3.3MI# N PACIFIC COAST HWY 27FT# E C/L 3FT# W PP NO 755043E + 150FT# NE PP NO 1111940E MKD (BM 56-6 RE 5869 1960)  | SY 5544   |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 734.898  | USC+GS BR CAP CONC FLUSH W/SURFACE @ SW COR<br>TOPANGA CYN BLVD + FERNWOOD PACIFIC DR TOP 4FT<br>DIA CONC BASE FOR STOP SIGN 80FT± S PP NO<br>340058E + 84FT±NW PP NO 821810E MKD (RS 20A<br>1925)  | SY 5545   |
| MALIBU<br>(1960) | 740.224  | USC+GS BR CAP CONC FLUSH W/SURFACE TOPANGA CYN<br>BLVD @ TOPANGA 4.0MI± N PACIFIC COAST HWY 300FT±<br>S TOPANGA POST OFFICE TOP W END S ABUT OLD<br>BRIDGE NO 2 + 49FT± SW C/L + 98FT± W PP NO<br>340067E MKD (A-50 1925)   | SY 5546   |
| MALIBU<br>(1960) | 770.580  | CS BR CAP BM MON CONC FLUSH WITH SURFACE @<br>TOPANGA CYN BLVD + BRIDGE NO 1282 OVER TOPANGA<br>CREEK ON RD TO TOPANGA ELEMENTRY SCHOOL 4.4MI±<br>N PACIFIC COAST HWY 0.4MI± N TOPANGA POST OFFICE<br>39FT± W OF W EDGE OF PVMT 19FT± N CTR BRIDGE<br>@ NE COR + 9FT± SW PP NO 1048042E MKD<br>(BM 56-9 RE 5869 1960)                                     | SY 5547   |
| MALIBU<br>(1960) | 807.194  | CS BR CAP CONC FLUSH W/SURFACE N TOPANGA CYN<br>BLVD 5.0MI± N PACIFIC COAST HWY 1.0MI± N TOPANGA<br>POST OFFICE S HIGHVALE TR S END CONC HDWL BY<br>MILEAGE MARKER (5 3MI) 12FT± E OF E EDGE PVMT +<br>63FT± S PP MKD (BM 56-10 1960 RE 5869)   | SY 5548   |
| MALIBU<br>(1960) | 837.230  | CS BR CAP 12IN BELOW SURFACE TOPANGA CYN BLVD NR<br>CULV 5.7MI± N PACIFIC COAST HWY OPP DRWY HSE NO<br>815 TOPANGA CYN BLVD 84FT± W PP NO 16652Y 82FT±<br>SE PP NO 16651Y + 12FT± S OF S EDGE PVMT MKD<br>(RESEDA A-12A 1960 RE 5869)   | SY 5549   |
| MALIBU<br>(1960) | 858.026  | CS MON CONC 8IN BELOW SURFACE @ TOE OF CUT IN<br>BANK TOPANGA CYN BLVD 225FT± NE ROBINSON RD<br>5.85MI± N PACIFIC COAST HWY 25FT± NE PP NO<br>16657Y BELOW TELEPHONE CONDUIT + 25FT± SE CTR<br>PVMT MKD (RESEDA A-12C 1960 RE 5869)   | SY 5550   |
| MALIBU<br>(1960) | 883.447  | USC+GS BR CAP CONC FLUSH W/SURFACE N TOPANGA<br>CYN BLVD @ HILLSIDE DR 5.6MI± N PACIFIC COAST<br>HWY 1.6MI± N TOPANGA POST OFFICE 35FT± W OF W<br>EDGE PVMT 106FT± NW FROM NW EDGE HILLSIDE DR<br>IN STEPS (PIER HALL) AMER LEGION POST NO 796<br>4FT± W OF E EDGE BLDG MKD (Z-49 1925)   | SY 5551   |
| MALIBU<br>(1960) | 937.804  | CS BR CAP TOP N CONC WINGWALL N TOPANGA CYN BLVD<br>@ CHENEY DR 6.3MI± N PACIFIC COAST HWY 2.3MI±N<br>TOPANGA POST OFFICE N WINGWALL CONC BRIDGE<br>NO 53-407 OVER GARAPITO CRK 82FT± NW OF NW SIDE<br>PVMT CHENEY DR 96FT± N PP NO 16687 + 63FT± SE<br>PP NO 25697Y MKD (BM 56-12 RE 5869 1960)  | SY 5552   |
| MALIBU<br>(1960) | 1080.071 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE N<br>TOPANGA CYN BLVD 7.1MI± N PACIFIC COAST HWY<br>3.1MI± N TOPANGA POST OFFICE 2.0MI± S SUMMIT<br>@ HORSESHOE TURN OF RD 188FT± SE OF S EDGE PVMT<br>3FT± E OF FIRE HYDRANT 114FT± S OF NW COR CONC<br>SODA STAND 126FT± SW CTR ROCK WISHING WELL +<br>126FT± W SPK CONC CULV MKD (BM 56-13 1960 RE<br>5869) | SY 5553   |
| MALIBU<br>(1960) | 1121.748 | CS BR CAP CONC 6IN BELOW SURFACE TOPANGA CYN<br>BLVD 1.7MI± S SUMMIT 0.1MI± W SANTA MARIA RD<br>30FT± W PP NO 17509Y 101FT± E PP NO 17510Y +<br>25FT± S OF S EDGE PVMT MKD (RESEDA A-10 1960 RE<br>5869)  | SY 5554   |
| MALIBU<br>(1960) | 1274.975 | CS BR CAP 12IN CONC POST 6IN ABOVE SURFACE @ N<br>TOPANGA CYN BLVD + ENTRADO DR 7.7MI± N PACIFIC<br>COAST HWY 1.3MI± S SUMMIT 39FT± S C/L<br>PROD FROM N OF N TOPANGA CYN BLVD 85FT± S PP NO<br>17525Y 116FT± W PP NO 17524Y 93FT± NW<br>PP NO 366352E + 3FT± S FIRE HYDRANT MKD (BM<br>56-14 1960 RE 5869)   | SY 5555   |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 1335.701 | CS BR CAP IN 12IN CONC POST 6IN ABOVE SURFACE N TOPANGA CYN BLVD 8.2MI± N PACIFIC COAST HWY 0.8MI± S SUMMIT 14FT± W OF W EDGE PVMT 3FT± SW FIRE HYDRANT NO N-51 93FT± N PP NO 1085767E + 93FT± SW PP NO 1085768E MKD (BM 56-15 1960 RE 5869)                  | SY 5556   |
| MALIBU<br>(1960) | 1499.850 | CS BR CAP IN WELL 11IN BELOW SURFACE @ TOPANGA CYN BLVD SUMMIT 2.8MI± S VENTURA BLVD 96FT± S OF SW COR (TOP-O-TOPANGA) BEER GARDEN CAFE 58FT± SW OF SW COR CONC BLOCK BLDG 74FT± NW PP NO 108579E + 51FT± NW FIRE HYDRANT NO N-53 MKD (BM 56-16 1960 RE 5869) | SY 5557   |
| MALIBU<br>(1960) | 1400.774 | LACE BR CAP CONC 3IN BELOW SURFACE TOPANGA CYN BLVD 0.2MI± N SUMMIT 410FT± N OF N EDGE PVMT ALONG PROMINENT RIDGE MKD (CITY OF LA DEPT OF PUBLIC WORKS 12-E-10 1938)  | SY 5558   |
| MALIBU<br>(1960) | 1287.422 | CS BR CAP LOWER WALL OF CONC CULV N TOPANGA CYN BLVD 2.1MI± S VENTURA BLVD 26FT± NE APPROX C/L + 113FT± N PP NO 637488H BY MILEAGE MARKER (A-10 4MI) MKD (BM 56-18 1960 RE 5869)  | SY 5559   |
| MALIBU<br>(1960) | 954.734  | CHIS SQ SE COR LAMP POST BASE @ TOPANGA CYN BLVD + DUMETZ RD 37FT± W + 32FT± N C/L INT MKD (USBM)   | SY 5560   |
| MALIBU<br>(1960) | 920.382  | LACE HEX BAR MON IN WELL 10IN BELOW SURFACE ON C/L TOPANGA CYN BLVD + 36FT± S C/L MARTINEZ ST   | SY 5561   |
| MALIBU<br>(1960) | 891.983  | DPW MON IN WELL 10IN BELOW SURFACE ON C/L TOPANGA CYN BLVD + 7FT± N C/L VENTURA BLVD MKD (CITY OF LA DEPT OF PUBLIC WORKS FIRST ORDER CONTROL 11-5-24 1941)   | SY 5562   |
| MALIBU<br>(1960) | 899.246  | LACE TRAVERSE MON ON C/L PI VENTURA BLVD 298FT± E C/L ALHAMA DR   | SY 5563   |
| MALIBU<br>(1960) | 130.328  | CSBM BR CAP CONC POST FLUSH 30FT± E CTR MALIBU CYN RD 0.2MI± N PACIFIC COAST HWY 235FT± N PAVED RD TO WEBSTER SCHOOL + R D MAINT YD NO 401 + 3FT± N PP NO 1210115E MKD (BM 57-1 RE 5869 1960)   | SY 5564   |
| MALIBU<br>(1960) | 219.609  | CSBM BR CAP 12IN CONC POST FLUSH 24FT± N C/L MALIBU CYN RD 0.5MI± N PACIFIC COAST HWY 100FT± E ROCK + CONC CULV NO 26+34 24FT± N C/L + 3FT± N GUY POLE NO 17343Y MKD (BM 57-2 RE 5869 1960)   | SY 5565   |
| MALIBU<br>(1960) | 342.245  | CS MON IN 12IN POST 4IN UP 21FT± NE APPROX C/L MALIBU CYN RD 0.9MI± N PACIFIC COAST HWY 18FT± SW FIRE HYDRANT + 67FT± NW PP NO 770707E MKD (BM 57-3 RE 5869 1960)   | SY 5566   |
| MALIBU<br>(1960) | 276.135  | CSBM BR CAP 12IN CONC POST 4IN ABOVE SURFACE 36FT± W APPROX C/L MALIBU CYN RD 1.2MI± N PACIFIC COAST HWY 1FT± E 3FT BARBED WIRE FENCE + 51FT± W PP NO 775300E + 2FT± W 3IN YELLOW IP MARKER MKD (BM 57-4 RE 5869 1960)  | SY 5567   |
| MALIBU<br>(1960) | 287.484  | CSBM BR CAP 12IN CONC POST 5IN ABOVE SURFACE 10FT± SW EDGE PVMT MALIBU CYN RD 1.7MI± N PACIFIC COAST HWY 240FT± NW CULV NO 88+17 8FT± S PP NO 775211E + 2FT± SW 3IN IP MARKER MKD (BM 57-5 RE 5869 1960)  | SY 5568   |
| MALIBU<br>(1960) | 385.651  | CSBM BR CAP CONC POST 4IN ABOVE SURFACE 10FT± SE EDGE PVMT MALIBU CYN RD 2.0MI± N PACIFIC COAST HWY 3FT± E PP NO 775217E + 280FT± SW PP + 2FT± S 3IN YELLOW IP MARKER MKD (BM 57-6 RE 5869)   | SY 5569   |

| QUAD-YEAR        | ELEV    | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|---------|---|-----------|
| MALIBU<br>(1960) | 480.009 | CSBM BR CAP 12IN CONC POST 4IN ABOVE SURFACE<br>33FT± E C/L MALIBU CYN RD 2.3MI± N PACIFIC<br>COAST HWY 13FT± E PP NO 775221E + 89FT± NE CTR<br>ROCK + CONC CULV NO 124+00 MKD (BM 57-7 RE 5869<br>1960)  | SY 5570   |
| MALIBU<br>(1960) | 505.167 | CSBM BR CAP BOULDER ROCK OUTCROP 35FT± SE C/L<br>PROD MALIBU CYN RD 2.7MI± N PACIFIC COAST HWY<br>93FT± S PP NO 1169253E 59FT± SW GUY POLE NO<br>1169254E + 195FT± S ROCK + CONC CULV NO 149+21<br>MKD (BM 57-8 RE 5869 1960)                   | SY 5571   |
| MALIBU<br>(1960) | 450.515 | CSBM BR CAP BOULDER ROCK OUTCROP 25FT± S APPROX<br>C/L MALIBU CYN RD 3.0MI± N PACIFIC COAST HWY<br>66FT± SW PP NO 1169261E 172FT± SE PP NO 1169265E<br>+ 235FT± E STA MARKER 162+93 MKD (BM 57-9 RE<br>5869 1960)                               | SY 5572   |
| MALIBU<br>(1960) | 375.708 | CSBM BR CAP 12IN CONC POST 4IN ABOVE SURFACE<br>43FT± SW APPROX C/L MALIBU CYN RD 3.3MI± N<br>PACIFIC COAST HWY 128FT± W PP NO 1169271E 21FT±<br>SW PP NO 189276E 13FT± SW OF NE FACE ROCK +<br>CONC CULV NO 177+28 MKD (BM 57-10 RE 5869 1960) | SY 5573   |
| MALIBU<br>(1960) | 459.827 | CSBM BR CAP 12IN CONC POST 4IN ABOVE SURFACE<br>40FT± E APPROX C/L MALIBU CYN RD 3.5MI± N<br>PACIFIC COAST HWY 250FT± S OF S END TUNNEL<br>NO B 994 22FT± N PP NO 1160279E + 75FT± E GUY<br>POLE NO 1169280E MKD (BM 57-11 RE 5869 1960)        | SY 5574   |
| MALIBU<br>(1960) | 461.059 | BT SPK TOP CONC CATCH BASIN NO 193+45 MALIBU<br>CYN RD 3.5MI± N PACIFIC COAST HWY @ SW END<br>TUNNEL NO B-994   | SY 5575   |
| MALIBU<br>(1960) | 463.400 | BT SPK IN WK @ NE COR TUNNEL NO B-994 MALIBU CYN<br>RD 3.5MI± N PACIFIC COAST HWY 2FT± INSIDE TUNNEL  | SY 5576   |
| MALIBU<br>(1960) | 448.146 | CSBM BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>23FT± E APPROX C/L MALIBU CYN RD 3.9MI± N<br>PACIFIC COAST HWY 120FT± N CULV NO 207+58 43FT±<br>E GUY POLE NO 1199445E + 3FT± N PP NO 1169288E<br>MKD (BM 57-11 RE 5869 1960)                   | SY 5577   |
| MALIBU<br>(1960) | 492.597 | 3/4IN IP + CAP W/DRILL HOLE 12IN ABOVE SURFACE<br>ON W SIDE LAS VIRGENES RD S OF ENT TAPIA PARK<br>66FT± S PP NO 1112170E 104FT± E PP NO 644159E<br>+ 94FT± SE 36IN OAK TREE MKD (C-1)  | SY 5578   |
| MALIBU<br>(1960) | 572.845 | CSBM MON 12IN CONC POST 4IN ABOVE SURFACE 27FT±<br>E C/L LAS VIRGENES RD 1.0MI± S MULHOLLAND HWY<br>52FT± S OF S EDGE RD TO CALABASAS RANCHO 2FT±<br>E PP NO 612475H MKD (BM 57-14 RE 5860 1960)  | SY 5579   |
| MALIBU<br>(1960) | 678.840 | CSBM BR CAP 12IN CONC POST 6IN ABOVE SURFACE<br>34FT± W C/L LAS VIRGENES RD 0.8MI± S MULHOLLAND<br>HWY 57FT± W PP NO 512470H + 320FT± S PP NO<br>612469H MKD (BM 57-14A RE 5869 1960)   | SY 5580   |
| MALIBU<br>(1960) | 596.209 | CSBM BR CAP 12IN CONC POST 4IN ABOVE SURFACE<br>OF N EDGE PVMT WAYCROSS RD + 0.5MI± S MULHOLLAND<br>HWY 73FT± E PP NO 351972E MKD (BM 57-15 RE 5869<br>1960)  | SY 5581   |
| MALIBU<br>(1960) | 589.006 | CS BR CAP IN WELL 8IN BELOW SURFACE 60FT± N<br>PI ON LAS VIRGENES RD @ MULHOLLAND HWY 24FT± S<br>COR 6FT CHAIN LINK FENCE 24FT± SW PP NO 1111323E<br>+ 68FT± NE PP NO 1111922E MKD (R17W R18W T1S 1<br>6 12 7 RE 5869)                          | SY 5582   |



| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 623.363  | CSBM MON IN WELL 9IN BELOW SURFACE 16FT± W APPROX C/L LAS VIRGENES RD 0.5MI± N MULHOLLAND HWY @ RD TO WHITE OAK RANCH (2577 LAS VIRGENES RD) 49FT± W PP NO 796029E 39FT± N GUY POLE NO 365666 + 9FT± SE SPK + TIN SW SIDE OF 36IN EUCALYPTUS TREE MKD (BM 57-17 RE 5869 1960) | SY 5583   |
| MALIBU<br>(1960) | 665.751  | CSBM BR CAP 12IN CONC POST 4IN ABOVE SURFACE 34FT± E C/L LAS VIRGENES RD 360FT± S DIRT RD TO PURPLE SAGE RANCH 1.0MI± N MULHOLLAND HWY 3FT± E PP NO 365677E 80FT± NE PP NO 612464H 775FT± N CULV NO 136+87 MKD (BM 57-18 RE 5869 1960)  | SY 5584   |
| MALIBU<br>(1960) | 699.923  | CSBM BR CAP 12IN CONC POST 4IN ABOVE SURFACE 10FT± NW C/L LAS VIRGENES RD PROD S 115FT± N DIRT RD TO E 1.5MI± N MULHOLLAND HWY @ STA MARKER 168+62 5FT± NW PP NO 572446H MKD (BM 57-19 RE 5869 1960)  | SY 5585   |
| MALIBU<br>(1960) | 725.174  | CSBM BR CAP CONC WK LAS VIRGENES SCHOOL LAS VIRGENES RD 10MI± S VENTURA BLVD 2FT± E FLAG POLE 55FT± NE OF SE COR SCHOOL OFFICE BLDG MKD (BM 57-20 RE 5869 1960)   | SY 5586   |
| MALIBU<br>(1960) | 756.672  | CSBM BR CAP IN 12IN CONC POST 4IN ABOVE SURFACE 23FT± E C/L LAS VIRGENES RD 0.5MI± S VENTURA BLVD @ RD TO NE TO TWIN OAKS RIDING ACADEMY 146FT± N ROCK + CONC CULV NO 230+21 + 3FT± N PP NO 855657E MKD (BM 57-21 RE 5869 1960)   | SY 5587   |
| MALIBU<br>(1960) | 770.859  | L+BN CONC BASE LIGHT STAND (FLOOD LIGHTS) IN PARK LOT (BILLINGSLEYS STEAK RANCH) 39FT± W + 320FT± S C/L INT VENTURA BLVD + LAS VIRGENES RD  | SY 5588   |
| MALIBU<br>(1960) | 832.001  | ALUMINUM CAP CONC MON 12IN BELOW TOP MEDIAN CB C/L VENTURA BLVD 0.5MI± E LAS VIRGENES RD + 8FT± W RADIUS POINT OF NOSE  | SY 5590   |
| MALIBU<br>(1960) | 905.234  | BR CAP MEDIAN STRIP VENTURA BLVD 18IN DN 1.05MI± E LAS VIRGENES RD  | SY 5591   |
| MALIBU<br>(1960) | 1001.481 | ST BR CAP 5IN BELOW MEDIAN CB VENTURA BLVD @ E 1.35MI± E LAS VIRGENES RD 4FT± W RADIUS PT   | SY 5592   |
| MALIBU<br>(1960) | 1056.586 | BR CAP VENTURA BLVD 4IN DN @ BC 1.55MI± E LAS VIRGENES RD   | SY 5593   |
| MALIBU<br>(1960) | 1119.583 | BR CAP MEDIAN STRIP 4IN DN C/L VENTURA BLVD EC 1.8MI± E LAS VIRGENES RD MKD (CSBM 57-27)  | SY 5594   |
| MALIBU<br>(1960) | 1047.617 | BR CAP 2IN IP 10IN DN C/L VENTURA BLVD 2.3MI± E LAS VIRGENES RD   | SY 5595   |
| MALIBU<br>(1960) | 1014.072 | BR CAP 2IN IP 10IN DN C/L VENTURA BLVD 2.5MI± E LAS VIRGENES RD   | SY 5596   |
| MALIBU<br>(1960) | 941.287  | BR CAP 2IN IP C/L VENTURA BLVD 3.0MI± E LAS VIRGENES RD   | SY 5597   |
| MALIBU<br>(1960) | 922.363  | ST HWY MON 8IN DN C/L VENTURA FRWY 165FT± E C/L MULHOLLAND DR OVERPASS BRIDGE NO 53 1067  | SY 5598   |
| MALIBU<br>(1960) | 915.191  | ST HWY BR CAP IN WELL 12IN DN @ C/L INT VENTURA BLVD + WOODLAKE AVE   | SY 5599   |
| MALIBU<br>(1960) | 888.743  | LACE MON IN WELL 9IN DN @ C/L INT VENTURA BLVD + FALLBROOK AVE MKD (TRAVERSE STA 11-D-22 1941)  | SY 5600   |

| QUAD-YEAR        | ELEV    | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM | NUMBER |
|------------------|---------|--|----|--------|
| MALIBU<br>(1960) | 880.587 | LACE MON IN WELL 10IN DN VENTURA BLVD 386FT± E SHOUP AVE 4FT± N OF N CB MEDIAN STRIP MKD (TRAVERSE STA 11-D-23 1941)       | SY | 5601   |
| MALIBU<br>(1960) | 773.914 | L+T CONC CB W TRAFFIC ISLAND C/L VENTURA BLVD 200FT± W C/L LAS VIRGENES RD   | SY | 5604   |
| MALIBU<br>(1960) | 757.794 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD 345FT± W RONDELL ST 0.3MI± W LAS VIRGENES RD                                 | SY | 5605   |
| MALIBU<br>(1960) | 778.704 | CHIS SQ NE COR CONC CATCH BASIN (DROP INLET) C/L VENTURA BLVD 0.5MI± W LAS VIRGENES RD                                     | SY | 5606   |
| MALIBU<br>(1960) | 801.446 | CHIS SQ SE COR CATCH BASIN (DROP INLET) ON C/L VENTURA BLVD 0.8MI± W LAS VIRGENES RD                                       | SY | 5607   |
| MALIBU<br>(1960) | 794.883 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD @ EC 0.85MI± W LAS VIRGENES RD   | SY | 5608   |
| MALIBU<br>(1960) | 778.878 | CHIS SQ @ SW COR CATCH BASIN (DROP INLET) C/L VENTURA BLVD 200FT± W C/L RONDELL ST 1.0MI± W LAS VIRGENES RD                | SY | 5609   |
| MALIBU<br>(1960) | 807.752 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD @ BC 1.1MI± W LAS VIRGENES RD  | SY | 5610   |
| MALIBU<br>(1960) | 878.552 | CHIS KNOB SE COR CONC CATCH BASIN (DROP INLET) C/L VENTURA BLVD 1.4MI± W LAS VIRGENES RD                                   | SY | 5611   |
| MALIBU<br>(1960) | 889.156 | FLT BR CAP 2IN IP CONC FLUSH 55FT± N C/L VENTURA BLVD BC STA 272+44.85 1.5MI W/O LAS VIRGENES RD                           | SY | 5612   |
| MALIBU<br>(1960) | 843.027 | CHIS SQ @ SE COR CATCH BASIN (DROP INLET) C/L VENTURA BLVD 1.7MI± W LAS VIRGENES RD  | SY | 5613   |
| MALIBU<br>(1960) | 830.065 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD @ BC 1.8MI± W LAS VIRGENES RD  | SY | 5614   |
| MALIBU<br>(1960) | 853.809 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD @ PCC 2.1MI ± W LAS VIRGENES RD  | SY | 5615   |
| MALIBU<br>(1960) | 856.731 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD @ EC 2.2MI± W LAS VIRGENES RD  | SY | 5616   |
| MALIBU<br>(1960) | 887.307 | CHIS KNOB NW COR CATCH BASIN (DROP INLET) C/L VENTURA BLVD 2.5MI± W LAS VIRGENES RD  | SY | 5617   |
| MALIBU<br>(1960) | 896.465 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD @ BC 2.55MI± W LAS VIRGENES RD   | SY | 5618   |
| MALIBU<br>(1960) | 907.920 | L+T MIDDLE W EDGE DROP INLET CATCH BASIN C/L VENTURA BLVD 100FT± E CHESEBRO RD 2.7MI± W LAS VIRGENES RD                    | SY | 5619   |
| MALIBU<br>(1960) | 904.450 | CHIS KNOB E END CONC GUARD RAIL S ROADWAY VENTURA BLVD 12FT± S C/L VENTURA BLVD 350FT± E LEWIS RD 3.2MI± W LAS VIRGENES RD | SY | 5620   |
| MALIBU<br>(1960) | 895.597 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD @ MPC 300FT± W LEWIS RD  | SY | 5621   |
| MALIBU<br>(1960) | 887.426 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD @ EC 900FT± W LEWIS RD   | SY | 5622   |
| MALIBU<br>(1960) | 879.841 | L+T E CB ISL C/L VENTURA BLVD 30FT± E C/L ROADSIDE DR 0.3MI± W LEWIS RD  | SY | 5623   |
| MALIBU<br>(1960) | 867.376 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD @ BC 0.65MI± W LEWIS RD  | SY | 5624   |

| QUAD-YEAR        | ELEV    | D E S C R I P T I O N<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|---------|---|-----------|
| MALIBU<br>(1960) | 864.570 | L+T CB W TRAFFIC ISL C/L VENTURA BLVD 32FT± W<br>C/L CORNELL RD 0.7MI± W LEWIS RD   | SY 5625   |
| MALIBU<br>(1960) | 858.492 | ALUMINUM CAP CONC MON 6IN BELOW MAC C/L VENTURA<br>BLVD @ W SIDE BRIDGE NO 5302R 0.1MI± W CORNELL<br>RD   | SY 5626   |
| MALIBU<br>(1960) | 865.975 | 1IN IP W/CO ENG TAG 6IN DN C/L VENTURA BLVD<br>500FT± E CANWOOD ST 0.3MI± W CORNELL RD  | SY 5627   |
| MALIBU<br>(1960) | 871.191 | L+T W MEDIAN CB C/L VENTURA BLVD 30FT± W C/L<br>CANWOOD DR (ROADSIDE DR TO S) 0.4MI± W<br>CORNELL RD  | SY 5628   |
| MALIBU<br>(1960) | 872.031 | ALUMINUM CAP CONC MON 4IM DN C/L VENTURA BLVD<br>0.6MI± W CORNELL RD 100FT± E ROSSLYN HOTEL SIGN<br>S SIDE VENTURA BLVD   | SY 5629   |
| MALIBU<br>(1960) | 872.072 | CHIS KNOB NW COR CATCH BASIN DROP INLET C/L<br>VENTURA BLVD 0.7MI± W CORNELL RD   | SY 5630   |
| MALIBU<br>(1960) | 880.680 | ALUMINUM CAP CONC MON 12IN DN C/L VENTURA BLVD<br>@ BC 0.8MI± W CORNELL RD  | SY 5631   |
| MALIBU<br>(1960) | 899.667 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD<br>@ EC 1.0MI± W CORNELL RD   | SY 5632   |
| MALIBU<br>(1960) | 906.859 | CHIS KNOB W END S BRIDGE INNER GUARD RAIL<br>(OVER LINDERA CREEK) 12FT± S C/L VENTURA BLVD<br>1.1MI± W CORNELL RD   | SY 5633   |
| MALIBU<br>(1960) | 907.871 | L+T W MEDIAN CB @ AGOURA RD (CANWOOD DR TO N)<br>ON C/L VENTURA BLVD 1.3MI± W CORNELL RD  | SY 5634   |
| MALIBU<br>(1960) | 922.792 | ALUMINUM CAP CONC MON 6IN DN @ C/L VENTURA BLVD<br>256FT E CANWOOD ST + 1.6MI W CORNELL RD  | SY 5635   |
| MALIBU<br>(1960) | 935.485 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD @<br>BC 500FT± E ENT TO (MELODY RANCH)<br>2.0MI± W CORNELL RD   | SY 5636   |
| MALIBU<br>(1960) | 943.427 | CHIS KNOB SW COR DROP INLET CATCH BASIN C/L<br>VENTURA BLVD 200FT± W ENT (MELODY<br>RANCH) 2.1MI± W CORNELL RD  | SY 5637   |
| MALIBU<br>(1960) | 960.472 | BR CAP CONC MON 6IN DN C/L VENTURA BLVD @<br>EC 2.4MI± W CORNELL RD   | SY 5638   |
| MALIBU<br>(1960) | 954.920 | CHIS KNOB NW COR DROP INLET CATCH BASIN C/L<br>VENTURA BLVD 2.5MI± W CORNELL RD   | SY 5639   |
| MALIBU<br>(1960) | 943.070 | ALUMINUM CAP CONC MON 6IN DN C/L VENTURA BLVD<br>2.7MI± W CORNELL RD  | SY 5640   |
| MALIBU<br>(1960) | 946.274 | CHIS SQ W SIDE CATCH BASIN (DROP INLET) C/L<br>VENTURA BLVD 3.0MI± W CORNELL RD   | SY 5641   |
| MALIBU<br>(1960) | 951.648 | CHIS SQ SE COR DROP INLET CATCH BASIN C/L<br>VENTURA BLVD 3.2MI± W CORNELL RD   | SY 5642   |
| MALIBU<br>(1960) | 958.810 | CHIS SQ E NOSE ISL CB C/L VENTURA BLVD 650FT± E<br>LA-VENTURA CO LINE 3.4MI± W CORNELL RD   | SY 5643   |
| MALIBU<br>(1960) | 949.117 | BR CAP 6IN DN C/L VENTURA BLVD @ LA-VENTURA CO<br>LINE 3.5MI± W CORNELL RD MKD (LA CO SUR RE 329<br>VENTURA-LOS ANGELES)  | SY 5644   |
| MALIBU<br>(1960) | 848.761 | CUT SPK + W IN CONC SLAB @ NW COR HSE NO 29002 @<br>SW COR CORNELL RD + OLD VENTURA BLVD 500FT± S<br>NEW VENTURA BLVD 58FT± S C/L OLD VENTURA BLVD<br>120FT± W C/L CORNELL RD | SY 5645   |

| QUAD-YEAR        | ELEV    | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|---------|---|-----------|
| MALIBU<br>(1960) | 807.700 | L+BN ROCK RUBBLE WINGWALL @ NW END SMALL SPILLWAY 22FT± W C/L CORNELL RD 0.65MI± S VENTURA BLVD   | SY 5646   |
| MALIBU<br>(1960) | 819.133 | L+BN CONC SQ S SIDE DRWY FARM HSE 20FT± W C/L CORNELL RD 0.8MI± S VENTURA BLVD  | SY 5647   |
| MALIBU<br>(1960) | 851.825 | CS MON N PL LA CO FIRE STA BATTALION NO 5 30FT± E C/L CORNELL RD 1.1MI± S VENTURA BLVD MKD (RE 2177)  | SY 5648   |
| MALIBU<br>(1960) | 844.935 | L+BN CONC CB NR S PL FIRE STA BATTALION NO 5 30FT± E C/L CORNELL RD 1.15MI± S VENTURA BLVD  | SY 5649   |
| MALIBU<br>(1960) | 799.141 | BT SPK ROCK RUBBLE WINGWALL SMALL SPILLWAY 13FT± W C/L CORNELL RD 1.2MI± S VENTURA BLVD   | SY 5650   |
| MALIBU<br>(1960) | 769.633 | L+BN ROCK RUBBLE WINGWALL SMALL SPILLWAY 13FT± W C/L CORNELL RD 1.9MI± S VENTURA BLVD   | SY 5651   |
| MALIBU<br>(1960) | 771.802 | L+BN TOP CONC PILLER S SIDE ENT TO PARAMOUNT MOVIE RANCH 25FT± W C/L CORNELL RD 2.5MI± S VENTURA BLVD 0.3MI± N MULHOLLAND HWY                           | SY 5652   |
| MALIBU<br>(1960) | 107.643 | L+BN N CB DIVIDER STRIP PACIFIC COAST HWY 45FT± E C/L LATIGO CANYON RD MKD (BM)   | SY 5894   |
| MALIBU<br>(1960) | 111.189 | L+BN NW COR CONC DROP INLET NR APPROX C/L PACIFIC COAST HWY 36FT± W C/L LATIGO CANYON RD MKD (BM)   | SY 5895   |
| MALIBU<br>(1960) | 188.790 | RDBM TAG S END W HDWL CULV 17+08 20FT± W C/L PVMT LATIGO CANYON RD 0.3MI± N PACIFIC COAST HWY   | SY 5896   |
| MALIBU<br>(1960) | 184.834 | RDBM TAG N END E HDWL CULV 17+08 35FT± E C/L PVMT LATIGO CANYON RD 0.3MI± N PACIFIC COAST HWY   | SY 5897   |
| MALIBU<br>(1960) | 397.795 | RDBM TAG @ ANG PT S HDWL CULV 56+35 21FT± S C/L PVMT LATIGO CANYON RD 1.0MI± N PACIFIC COAST HWY  | SY 5898   |
| MALIBU<br>(1960) | 401.705 | RDBM TAG E END N HDWL CULV 56+35 30FT± N C/L PVMT LATIGO CANYON RD 1.0MI± N PACIFIC COAST HWY   | SY 5899   |
| MALIBU<br>(1960) | 460.793 | L+BN SE COR CONC BOX NR CULV 69+70 30FT± W C/L PVMT LATIGO CANYON RD 1.4MI± N PACIFIC COAST HWY MKD (BM)  | SY 5900   |
| MALIBU<br>(1960) | 458.244 | L+BN CONC FOOTING OF CARPORT @ HSE NO 5445 NR CULV 69+70 60FT± W C/L PVMT LATIGO CANYON RD 1.4MI± N PACIFIC COAST HWY MKD (BM)                          | SY 5901   |
| MALIBU<br>(1960) | 664.159 | RDBM MON IN WELL 10IN DN NR PI 58FT± W C/L PVMT LATIGO CANYON RD 2.0MI± N PACIFIC COAST HWY 2IN IP MARKER 2FT± W  | SY 5902   |
| MALIBU<br>(1960) | 682.460 | RDBM MON IN WELL 10IN DN NR BC 30FT± W C/L PVMT LATIGO CANYON RD 2.1MI± N PACIFIC COAST HWY 2IN IP MARKER 2FT± W  | SY 5903   |
| MALIBU<br>(1960) | 796.891 | RDBM TAG CONC FOOTING @ W GATE POST PRIVATE DRWY NR DRAINAGE PIPE 125+80 30FT± S C/L PVMT LATIGO CANYON RD 2.5MI± N PACIFIC COAST HWY                   | SY 5904   |
| MALIBU<br>(1960) | 800.620 | RDBM MON IN WELL 10IN DN NR DRAINAGE PIPE 125+80 40FT± S C/L PVMT LATIGO CANYON RD 15FT± W PRIVATE DRWY 2.5MI± N PACIFIC COAST HWY 2IN IP MARKER 2FT± S | SY 5905   |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 998.615  | RDBM TAG NR CTR OF GAS ISLAND SE COR LATIGO CANYON RD + OCEAN VIEW DR 30FT± S + 20FT± E C/L INT   | SY 5906   |
| MALIBU<br>(1960) | 1003.566 | RDBM TAG ABANDONED CONC GAS ISLAND NE COR LATIGO CANYON RD + OCEAN VIEW DR 75FT± N + 24FT± E C/L INT  | SY 5907   |
| MALIBU<br>(1960) | 1125.673 | RDBM MON IN WELL 10IN DN NR DRAINAGE PIPE 181+60 22FT± E C/L PVMT LATIGO CANYON RD 0.5MI± N OCEAN VIEW DR 2IN IP MARKER 2FT±E                           | SY 5908   |
| MALIBU<br>(1960) | 1134.236 | RDBM MON IN WELL 10IN DN NR DRAINAGE PIPE 181+60 18FT± E C/L PVMT LATIGO CANYON RD 0.6MI± N OCEAN VIEW DR 2IN IP MARKER 2FT±E                           | SY 5909   |
| MALIBU<br>(1960) | 1186.563 | RDBM MON IN WELL 10IN DN NR DRAINAGE PIPE 207+79 27FT± W C/L PVMT LATIGO CANYON RD 1.1MI± N OCEAN VIEW DR 2IN IP MARKER 2FT± W                          | SY 5910   |
| MALIBU<br>(1960) | 1188.783 | RDBM TAG IN ROCK NR DRAINAGE PIPE 207+79 ON DAYLIGHT OF CURVE 10FT± W APPROX PI + 30FT± W C/L PVMT LATIGO CANYON RD 1.1MI± N OCEAN VIEW DR              | SY 5911   |
| MALIBU<br>(1960) | 1281.238 | RDBM MON IN WELL 10IN DN NR DRAINAGE PIPE 238+64 15FT± E C/L PVMT LATIGO CANYON RD 1.5MI± N OCEAN VIEW DR 2IN IP MARKER 2FT± SE                         | SY 5912   |
| MALIBU<br>(1960) | 1302.940 | RDBM MON IN WELL 10IN DN NR DRAINAGE PIPE 238+64 15FT± W C/L PVMT LATIGO CANYON RD 1.5MI± N OCEAN VIEW DR 2IN IP MARKER 2FT± W                          | SY 5913   |
| MALIBU<br>(1960) | 1457.175 | RDBM TAG CONC FOOTING OF 4IN IP GATE POST TO DIRT RD NR DRAINAGE PIPE 268+05 50FT± W C/L PVMT LATIGO CANYON RD 2.1MI± N OCEAN VIEW DR                   | SY 5914   |
| MALIBU<br>(1960) | 1463.913 | RDBM MON IN WELL 10IN DN @ END STEEL GUARD RAIL NR DRAINAGE PIPE 268+05 30FT± NW C/L PVMT LATIGO CANYON RD 2.1MI± N OCEAN VIEW DR 2IN IP MARKER 2FT±NW  | SY 5915   |
| MALIBU<br>(1960) | 1610.678 | RDBM MON IN WELL 10IN DN NR DRAINAGE PIPE 297+41 OPP END STEEL GUARD RAIL 20FT± W C/L PVMT LATIGO CANYON RD 2.7MI± N OCEAN VIEW DR 2IN IP MARKER 2FT± W | SY 5916   |
| MALIBU<br>(1960) | 1614.282 | RDBM MON IN WELL 10IN DN NR DRAINAGE PIPE 297+41 BACK STEEL GUARD RAIL 24FT± W C/L PVMT LATIGO CANYON RD 2.7MI± N OCEAN VIEW DR 2IN IP MARKER 2FT± W    | SY 5917   |
| MALIBU<br>(1960) | 1803.385 | RDBM TAG CONC + ROCK RETAINING WALL 19FT± S C/L PVMT LATIGO CANYON RD 3.2MI± N OCEAN VIEW DR  | SY 5918   |
| MALIBU<br>(1960) | 1805.823 | RDBM MON IN WELL 10IN DN NR W END CONC + ROCK RETAINING WALL 18FT± S C/L PVMT LATIGO CANYON RD 3.2MI± N OCEAN VIEW DR 2IN IP MARKER 2FT± S              | SY 5919   |
| MALIBU<br>(1960) | 1988.658 | RDBM MON IN WELL 10IN DN NR DRAINAGE PIPE 354+67 33FT± W C/L PVMT LATIGO CANYON RD 3.7MI± N OCEAN VIEW DR 2IN IP MARKER 2FT± W                          | SY 5920   |
| MALIBU<br>(1960) | 1989.539 | RDBM MON IN WELL 10IN DN NR DRAINAGE PIPE 354+67 40FT± E C/L PVMT LATIGO CANYON RD 3.7MI± N OCEAN VIEW DR 2IN IP MARKER 2FT± E                          | SY 5921   |
| MALIBU<br>(1960) | 2087.169 | 3/4IN IP + CD ENG TAG 4IN UP ON SEMI-TANG OF CURVE 175FT±N APPROX C/L NEWTON FIRE RD + 40FT± W C/L PVMT LATIGO CANYON RD 4.0MI± N OCEAN VIEW DR         | SY 5923   |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM | NUMBER |
|------------------|----------|--|----|--------|
| MALIBU<br>(1960) | 1955.115 | RDBM MON IN WELL 10IN DN 30FT± E C/L PVMT LATIGO CANYON RD 4.6MI± N OCEAN VIEW DR 2IN IP MARKER 2FT± E                             | SY | 5924   |
| MALIBU<br>(1960) | 1943.111 | RDBM MON IN WELL 10IN DN 20FT± W C/L PVMT LATIGO CANYON RD 4.6MI± N OCEAN VIEW DR 2IN IP MARKER 2FT± W                             | SY | 5925   |
| MALIBU<br>(1960) | 1780.588 | CS MON 6IN UP ON NW COR LATIGO CANYON RD + NEWTON CANYON RD 50FT± N + 18FT± W C/L INT MKD (BM D-6)                                 | SY | 5926   |
| MALIBU<br>(1960) | 1787.340 | RDBM TAG IN ROCK LEDGE 8IN UP NE COR LATIGO CANYON RD + NEWTON CANYON RD 125FT± N + 18FT± E C/L INT                                | SY | 5927   |
| MALIBU<br>(1960) | 1978.643 | RDBM MON IN WELL 10IN DN NR END STEEL GUARD RAIL 15FT± S C/L PVMT LATIGO CANYON RD 0.7MI± N NEWTON CANYON RD 2IN IP MARKER 2FT± S  | SY | 5928   |
| MALIBU<br>(1960) | 1984.985 | RDBM TAG IN ROCK LEDGE ON INSIDE CURVE 18FT± E C/L PVMT LATIGO CANYON RD 0.7MI± N NEWTON CANYON RD MKD W/ARROW                     | SY | 5929   |
| MALIBU<br>(1960) | 2120.554 | RDBM TAG IN LARGE BOULDER FLUSH 85FT± W C/L PVMT LATIGO CANYON RD + 15FT± N C/L PROD CASTRO PEAK FIRE RD 1.2MI± N NEWTON CANYON RD | SY | 5930   |
| MALIBU<br>(1960) | 2121.148 | RDBM TAG IN CONC FOOTING S GATE POST TO CASTRO PEAK FIRE RD 75FT± E C/L PVMT LATIGO CANYON RD 1.2MI± N NEWTON CANYON RD            | SY | 5931   |
| MALIBU<br>(1960) | 1952.295 | CS BM MON 6IN UP ON NE COR LATIGO CANYON RD + BACKUS RD 30FT± N + 27FT± E C/L INT MKD (BM D-1-B)                                   | SY | 5932   |
| MALIBU<br>(1960) | 1943.391 | RDBM TAG IN LARGE BOULDER ON NW COR LATIGO CANYON RD + BACKUS RD 185FT± N + 23FT± W C/L INT  | SY | 5933   |
| MALIBU<br>(1960) | 1703.820 | RDBM TAG LARGE BOULDER NW COR BACKUS RD + BARBARA LANE 46FT± W + 18FT± N C/L INT   | SY | 5934   |
| MALIBU<br>(1960) | 1696.118 | STEEL ROD IN N WING WALL OF BRIDGE B 929 ON SW COR BACKUS RD + BARBARA LANE 118FT± W + 30FT± S C/L INT MKD W/(X)                   | SY | 5935   |
| MALIBU<br>(1960) | 180.926  | L+T HDWL NW COR PACIFIC COAST HWY + ENCINAL CANYON RD  | SY | 6332   |
| MALIBU<br>(1960) | 238.022  | SPK+T PP 1308414E 21FT± S C/L ENCINAL CANYON RD 0.3MI± N PACIFIC COAST HWY   | SY | 6333   |
| MALIBU<br>(1960) | 240.711  | L+T W HDWL 23FT± S C/L ENCINAL CANYON RD 0.3MI± N PACIFIC COAST HWY MKD (BM)   | SY | 6334   |
| MALIBU<br>(1960) | 293.174  | R D MON 10IN DN @ EC ENCINAL CANYON RD 0.45MI± N PACIFIC COAST HWY MKD (BM)  | SY | 6335   |
| MALIBU<br>(1960) | 298.771  | SPK+T PP 1330716E 23FT± S C/L ENCINAL CANYON RD 0.45MI± N PACIFIC COAST HWY  | SY | 6336   |
| MALIBU<br>(1960) | 384.420  | R D MON 10IN DN @ BC ENCINAL CANYON RD 0.7MI± N PACIFIC COAST HWY MKD (BM)   | SY | 6337   |
| MALIBU<br>(1960) | 409.375  | SPK+T PP 1308443E NW COR ENCINAL CANYON RD + AVENIDA DE LA ENCINAL 20FT± N + 45FT± W C/L INT                                       | SY | 6338   |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 415.039  | R D MON 10IN DN @ PI ENCINAL CANYON RD 0.85MI± N SY<br>PACIFIC COAST HWY MKD (BM)                   | 6339      |
| MALIBU<br>(1960) | 470.820  | RDBM TAG ROCK HDWL 35FT± N C/L ENCINAL CANYON RD SY<br>1.0MI± N PACIFIC COAST HWY                   | 6340      |
| MALIBU<br>(1960) | 478.070  | R D MON 10IN DN @ BC ENCINAL CANYON RD 1.0MI± N SY<br>PACIFIC COAST HWY MKD (BM)                    | 6341      |
| MALIBU<br>(1960) | 521.241  | L+T E ROCK HDWL 20FT± S C/L ENCINAL CANYON RD SY<br>1.2MI± N PACIFIC COAST HWY MKD (BM)             | 6342      |
| MALIBU<br>(1960) | 548.097  | R D MON 10IN DN @ EC ENCINAL CANYON RD 1.3MI± N SY<br>PACIFIC COAST HWY MKD (BM)                    | 6343      |
| MALIBU<br>(1960) | 600.241  | L+T ANG PT ROCK WALL 20FT± N C/L ENCINAL CANYON SY<br>RD 1.5MI± N PACIFIC COAST HWY MKD (BM)        | 6344      |
| MALIBU<br>(1960) | 618.444  | R D MON 10IN DN @ EC ENCINAL CANYON RD 1.55MI± N SY<br>PACIFIC COAST HWY MKD (BM)                   | 6345      |
| MALIBU<br>(1960) | 670.369  | RDBM TAG S HDWL DRAIN 17FT± W C/L ENCINAL CANYON SY<br>RD 1.7MI± N PACIFIC COAST HWY                | 6346      |
| MALIBU<br>(1960) | 676.056  | R D MON 10IN DN @ EC ENCINAL CANYON RD 1.7MI± N SY<br>PACIFIC COAST HWY MKD (BM)                    | 6347      |
| MALIBU<br>(1960) | 737.046  | R D MON 10IN DN @ EC ENCINAL CANYON RD 1.95MI± N SY<br>PACIFIC COAST HWY MKD (BM)                   | 6348      |
| MALIBU<br>(1960) | 756.015  | RDBM TAG S ROCK WALL DRAIN 20FT± E C/L ENCINAL SY<br>CANYON RD 2.0MI± N PACIFIC COAST HWY           | 6349      |
| MALIBU<br>(1960) | 810.018  | R D MON 10IN DN @ PI ENCINAL CANYON RD 2.2MI± N SY<br>PACIFIC COAST HWY MKD (BM)                    | 6350      |
| MALIBU<br>(1960) | 824.630  | L+T ROCK WALL DRAIN 18FT± W C/L ENCINAL CANYON SY<br>RD 2.25MI± N PACIFIC COAST HWY MKD (BM)        | 6351      |
| MALIBU<br>(1960) | 859.219  | RDBM TAG ANG PT S ROCK WALL DRAIN 21FT± W C/L SY<br>ENCINAL CANYON RD 2.35MI± N PACIFIC COAST HWY   | 6352      |
| MALIBU<br>(1960) | 864.793  | R D MON 10IN DN @ PI ENCINAL CANYON RD 2.35MI± N SY<br>PACIFIC COAST HWY MKD (BM)                   | 6353      |
| MALIBU<br>(1960) | 923.648  | RDBM TAG N ROCK WALL DRAIN 20FT± W C/L ENCINAL SY<br>CANYON RD 2.55MI± N PACIFIC COAST HWY MKD (BM) | 6354      |
| MALIBU<br>(1960) | 934.881  | R D MON 10IN DN @ PI ENCINAL CANYON RD 2.6MI± N SY<br>PACIFIC COAST HWY MKD (BM)                    | 6355      |
| MALIBU<br>(1960) | 1007.537 | R D MON 10IN DN @ BC ENCINAL CANYON RD 2.85MI± SY<br>N PACIFIC COAST HWY MKD (BM)                   | 6356      |
| MALIBU<br>(1960) | 1022.952 | L+T S ROCK WALL DRAIN 21FT± W C/L ENCINAL CANYON SY<br>RD 2.9MI± N PACIFIC COAST HWY MKD (BM)       | 6357      |
| MALIBU<br>(1960) | 1105.504 | R D MON 10IN DN @ PI ENCINAL CANYON RD 3.2MI± N SY<br>PACIFIC COAST HWY MKD (BM)                    | 6358      |
| MALIBU<br>(1960) | 1124.750 | L+T N ROCK HDWL 100FT± E C/L ENCINAL CANYON RD SY<br>3.25MI± N PACIFIC COAST HWY MKD (BM)           | 6359      |
| MALIBU<br>(1960) | 1148.621 | R D MON 8IN DN @ BC ENCINAL CANYON RD 3.35MI± N SY<br>PACIFIC COAST HWY MKD (BM)                    | 6360      |
| MALIBU<br>(1960) | 1154.294 | R D MON 10IN DN @ EC ENCINAL CANYON RD 3.4MI± N SY<br>PACIFIC COAST HWY MKD (BM)                    | 6361      |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM NUMBER |
|------------------|----------|--|-----------|
| MALIBU<br>(1960) | 1185.979 | R D MON 10IN DN @ BC ENCINAL CANYON RD 3.6MI± N<br>PACIFIC COAST HWY MKD (BM)                  | SY 6362   |
| MALIBU<br>(1960) | 1183.782 | L+T E ROCK WALL DRAIN 50FT± S C/L ENCINAL CANYON<br>RD 3.6 MI± N PACIFIC COAST HWY MKD (BM)    | SY 6363   |
| MALIBU<br>(1960) | 1219.817 | L+T E ROCK WALL DRAIN 70FT± N C/L ENCINAL CANYON<br>RD 3.8MI±N PACIFIC COAST HWY MKD (BM)      | SY 6364   |
| MALIBU<br>(1960) | 1223.013 | R D MON 10IN DN @ EC ENCINAL CANYON RD 3.8MI± N<br>PACIFIC COAST HWY MDK (BM)                  | SY 6365   |
| MALIBU<br>(1960) | 1305.288 | RDBM TAG CONC FLOOR DRAIN 20FT± S C/L ENCINAL<br>CANYON RD 4.1MI± N PACIFIC COAST HWY MKD (BM) | SY 6366   |
| MALIBU<br>(1960) | 1312.353 | R D MON 10IN DN @ BC ENCINAL CANYON RD 4.1MI±N<br>PACIFIC COAST HWY MKD (BM)                   | SY 6367   |
| MALIBU<br>(1960) | 1372.447 | R D MON 8IN DN @ POST ENCINAL CANYON RD 98FT±<br>S PI 4.35MI± N PACIFIC COAST HWY MKD (BM)     | SY 6368   |
| MALIBU<br>(1960) | 1381.176 | R D MON 10IN DN @ POST ENCINAL CANYON RD<br>94FT± N PI 4.4MI± N PACIFIC COAST HWY MKD (BM)     | SY 6369   |
| MALIBU<br>(1960) | 1412.847 | SPK+T PP 1090666E 24FT± S C/L ENCINAL CANYON RD<br>4.55MI±N PACIFIC COAST HWY                  | SY 6370   |
| MALIBU<br>(1960) | 1414.895 | R D MON 10IN DN @ POST ENCINAL CANYON RD<br>96FT± E BC 4.55MI± N PACIFIC COAST HWY MKD (BM)    | SY 6371   |
| MALIBU<br>(1960) | 1450.968 | L+T ROCK WALL DRAIN 50FT± E C/L ENCINAL CANYON<br>RD 4.65MI±N PACIFIC COAST HWY                | SY 6372   |
| MALIBU<br>(1960) | 1460.494 | R D MON 10IN DN @ POST ENCINAL CANYON RD<br>224FT± S BC 4.65MI± N PACIFIC COAST HWY            | SY 6373   |
| MALIBU<br>(1960) | 1496.514 | R D MON 6IN DN @ PI ENCINAL CANYON RD 4.75MI±<br>N PACIFIC COAST HWY                           | SY 6374   |
| MALIBU<br>(1960) | 1514.718 | RDBM TAG CONC FLOOR DRAIN 17FT± W C/L ENCINAL<br>CANYON RD 4.8MI± N PACIFIC COAST HWY          | SY 6375   |
| MALIBU<br>(1960) | 1565.415 | RDBM TAG CONC FLOOR DRAIN 19FT± W C/L ENCINAL<br>CANYON RD 5.0MI± N PACIFIC COAST HWY          | SY 6376   |
| MALIBU<br>(1960) | 1566.841 | R D MON 10IN DN @ POST ENCINAL CANYON RD<br>99FT± N EC 5.0MI± N PACIFIC COAST HWY MKD (BM)     | SY 6377   |
| MALIBU<br>(1960) | 1600.612 | RDBM TAG CONC FLOOR DRAIN 19FT± E C/L ENCINAL<br>CANYON RD 5.3MI± N PACIFIC COAST HWY          | SY 6378   |
| MALIBU<br>(1960) | 1605.766 | R D MON 8IN DN @ PI ENCINAL CANYON RD 5.3MI± N<br>PACIFIC COAST HWY MKD (BM) 2IN IP MKR 2FT S  | SY 6379   |
| MALIBU<br>(1960) | 1643.607 | SPK+T PP 1090694E NE COR ENCINAL CANYON RD +<br>DECKER RD 24FT± N + 126FT± E C/L INT           | SY 6380   |
| MALIBU<br>(1960) | 1643.130 | R D MON 12IN DN @ BC ENCINAL CANYON RD 26FT±<br>E C/L DECKER RD MKD (BM)                       | SY 6381   |
| MALIBU<br>(1960) | 1670.894 | SPK+T TP 1362 25FT± E C/L DECKER RD 0.2MI±<br>N ENCINAL CANYON RD                              | SY 6382   |
| MALIBU<br>(1960) | 1666.555 | 1 1/2IN IP @ PROPERTY COR 18FT± E C/L DECKER RD<br>0.25MI±N ENCINAL CANYON RD NR TP 1362       | SY 6383   |
| MALIBU<br>(1960) | 1596.040 | SPK+T TP 1354 45FT± E C/L DECKER RD 0.5MI±N<br>ENCINAL CANYON RD                               | SY 6384   |



| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 1587.008 | DATE NAIL PP 664587E 20FT± W C/L DECKER RD<br>0.5MI± N ENCINAL CANYON RD                      | SY 6385   |
| MALIBU<br>(1960) | 1517.210 | N+T LARGE ROCK SE COR DECKER RD + MULHOLLAND<br>HWY 22FT± E + 50FT± S C/L INT MKD (ANG PT)    | SY 6386   |
| MALIBU<br>(1960) | 1039.562 | RDBM TAG CONC FLOOR DRAIN 21FT± W C/L MULHOLLAND<br>HWY + 20FT± S C/L STUNT RD                | SY 6387   |
| MALIBU<br>(1960) | 1027.662 | L+T CTR ROCK HDWL 15FT± S C/L STUNT RD + 185FT±<br>E C/L MULHOLLAND HWY MKD (BM)              | SY 6388   |
| MALIBU<br>(1960) | 1056.368 | RDBM TAG S ROCK WALL DRAIN 18FT± W C/L STUNT RD<br>0.3MI± S MULHOLLAND HWY NR BC              | SY 6389   |
| MALIBU<br>(1960) | 1057.576 | RDBM TAG ROCK HDWL 35FT± E C/L STUNT RD 0.3MI±<br>S MULHOLLAND HWY NR STA POST 195+86         | SY 6390   |
| MALIBU<br>(1960) | 1142.637 | L+T ROCK HDWL 21FT± E C/L STUNT RD 0.6MI± S<br>MULHOLLAND HWY NR STA POST 181+31              | SY 6391   |
| MALIBU<br>(1960) | 1147.102 | RDBM TAG ROCK HDWL 15FT± E C/L STUNT RD 0.6MI±<br>S MULHOLLAND HWY NR STA POST 179+85         | SY 6392   |
| MALIBU<br>(1960) | 1236.802 | RDBM TAG ROCK WALL DRAIN 16FT± S C/L STUNT RD<br>1.0MI± S MULHOLLAND HWY                      | SY 6393   |
| MALIBU<br>(1960) | 1250.238 | RDBM TAG ROCK HDWL 16FT± N C/L STUNT RD 1.05MI±<br>S MULHOLLAND HWY NR STA POST 159+39        | SY 6394   |
| MALIBU<br>(1960) | 1330.023 | RDBM TAG ROCK HDWL 12FT± S C/L STUNT RD 1.35MI±<br>S MULHOLLAND HWY NR STA POST 143+66        | SY 6395   |
| MALIBU<br>(1960) | 1365.332 | RDBM TAG ROCK WALL DRAIN 18FT± W C/L STUNT RD<br>1.45MI± S MULHOLLAND HWY                     | SY 6396   |
| MALIBU<br>(1960) | 1397.596 | RDBM TAG ROCK HDWL 21FT± SE C/L STUNT RD<br>1.5MI± S MULHOLLAND HWY NR STA POST 134+39        | SY 6397   |
| MALIBU<br>(1960) | 1434.291 | 1 1/2 IN IP + RD TAG 40FT± N C/L STUNT RD 1.6MI±<br>S MULHOLLAND HWY MKD (L6)                 | SY 6398   |
| MALIBU<br>(1960) | 1499.540 | RDBM TAG ROCK WALL DRAIN 21FT± N C/L STUNT RD<br>1.85MI± S MULHOLLAND HWY                     | SY 6399   |
| MALIBU<br>(1960) | 1506.541 | RDBM TAG ROCK WING WALL 25FT± S C/L STUNT RD<br>1.85MI± S MULHOLLAND HWY NR STA POST 119+48   | SY 6400   |
| MALIBU<br>(1960) | 1606.172 | SPK+T PP 1143559E 16FT± NW C/L STUNT RD 2.15MI±<br>S MULHOLLAND HWY                           | SY 6401   |
| MALIBU<br>(1960) | 1608.458 | RDBM TAG ROCK WALL DRAIN 28FT± SE C/L STUNT RD<br>2.15MI± S MULHOLLAND HWY NR STA POST 104+41 | SY 6402   |
| MALIBU<br>(1960) | 1718.648 | RDBM TAG ROCK WALL DRAIN 35FT± S C/L STUNT RD<br>2.5MI± S MULHOLLAND HWY NR STA POST 87+80    | SY 6403   |
| MALIBU<br>(1960) | 1728.246 | RDBM TAG ROCK WALL DRAIN 20FT± S C/L STUNT RD<br>2.5MI± S MULHOLLAND HWY                      | SY 6404   |
| MALIBU<br>(1960) | 1806.659 | SPK+T PP 1143576E 30FT± SW C/L STUNT RD 2.7MI±<br>S MULHOLLAND HWY                            | SY 6405   |
| MALIBU<br>(1960) | 1810.800 | PK ROCK HDWL 25FT± SW C/L STUNT RD 2.7MI± S<br>MULHOLLAND HWY                                 | SY 6406   |
| MALIBU<br>(1960) | 1926.569 | RDBM TAG ROCK WALL DRAIN 20FT± N C/L STUNT RD<br>2.95MI± S MULHOLLAND HWY                     | SY 6407   |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 1934.973 | RDBM TAG ROCK WALL DRAIN 20FT± S C/L STUNT RD<br>2.95MI± S MULHOLLAND HWY NR STA POST 59+79               | SY 6408   |
| MALIBU<br>(1960) | 2035.989 | RDBM TAG ROCK WALL DRAIN 18FT± N C/L STUNT RD<br>3.3MI± S MULHOLLAND HWY                                  | SY 6409   |
| MALIBU<br>(1960) | 2042.308 | RDBM TAG ROCK HDWL 21FT± S C/L STUNT RD 3.3MI±<br>S MULHOLLAND HWY NR STA POST 47+20                      | SY 6410   |
| MALIBU<br>(1960) | 2141.179 | RDBM TAG ROCK HDWL 24FT± S C/L STUNT RD 3.6MI±<br>S MULHOLLAND HWY NR STA POST 34+45                      | SY 6411   |
| MALIBU<br>(1960) | 2172.198 | RDBM TAG ROCK HDWL 21FT± S C/L STUNT RD<br>3.65MI± S MULHOLLAND HWY NR STA POST 31+10                     | SY 6412   |
| MALIBU<br>(1960) | 2268.957 | RDBM TAG ROCK HDWL 16FT± S C/L STUNT RD 3.95MI±<br>S MULHOLLAND HWY NR STA POST 15+68                     | SY 6413   |
| MALIBU<br>(1960) | 2266.646 | RDBM TAG ROCK HDWL 20FT± N C/L STUNT RD 3.95MI±<br>S MULHOLLAND HWY                                       | SY 6414   |
| MALIBU<br>(1960) | 2366.626 | ROUND HD SPK ROCK WALL DRAIN SE COR STUNT RD +<br>SADDLE PEAK RD 15FT± S + 45FT± E C/L INT<br>MKD (SP 13) | SY 6415   |
| MALIBU<br>(1960) | 2355.569 | RDBM TAG ROCK HDWL DRAIN SW COR STUNT RD +<br>SCHUEREN RD 15FT± S + 300FT± W C/L INT                      | SY 6416   |
| MALIBU<br>(1960) | 2327.453 | RDBM TAG ROCK WALL DRAIN 16FT± S C/L SCHUEREN<br>RD 0.2MI± SW STUNT RD                                    | SY 6417   |
| MALIBU<br>(1960) | 2308.437 | RDBM TAG ROCK WALL 25FT± E C/L SCHUEREN RD<br>0.25MI± SW STUNT RD OPP STA POST 80+74                      | SY 6418   |
| MALIBU<br>(1960) | 2249.387 | RDBM TAG LARGE ROCK 40FT± W C/L SCHUEREN RD<br>0.4MI± SW STUNT RD   | SY 6419   |
| MALIBU<br>(1960) | 2235.634 | RDBM TAG ROCK HDWL 23FT± N C/L SCHUEREN RD<br>0.45MI± SW STUNT RD NR STA POST 69+51                       | SY 6420   |
| MALIBU<br>(1960) | 2188.100 | RDBM TAG N END ROCK WALL DRAIN 15FT± W C/L<br>SCHUEREN RD 0.7MI± SW STUNT RD                              | SY 6421   |
| MALIBU<br>(1960) | 2165.269 | RDBM TAG ROCK HDWL 35FT± E C/L SCHUEREN RD<br>0.75MI± SW STUNT RD   | SY 6422   |
| MALIBU<br>(1960) | 2126.758 | RDBM TAG ROCK HDWL 20FT± W C/L SCHUEREN RD<br>0.9MI± SW STUNT RD NR STA POST 47+67                        | SY 6423   |
| MALIBU<br>(1960) | 2121.307 | RDBM TAG LARGE BOULDER 40FT± E C/L SCHUEREN RD<br>0.95MI± SW STUNT RD NR BC                               | SY 6424   |
| MALIBU<br>(1960) | 2057.039 | RDBM TAG ROCK HDWL 15FT± N C/L SCHUEREN RD<br>1.15MI± SW STUNT RD NR STA POST 35+49                       | SY 6425   |
| MALIBU<br>(1960) | 2049.564 | RDBM TAG ROCK LEDGE 22FT± N C/L SCHUEREN RD<br>1.2MI± SW STUNT RD   | SY 6426   |
| MALIBU<br>(1960) | 1967.660 | RDBM TAG ROCK HDWL 24FT± NW C/L SCHUEREN RD<br>1.4MI± SW STUNT RD NR STA POST 22+53                       | SY 6427   |
| MALIBU<br>(1960) | 1953.192 | RDBM TAG ROCK WALL DRAIN 18FT± S C/L SCHUEREN RD<br>1.45MI± SW STUNT RD OPP STA POST 20+32                | SY 6428   |
| MALIBU<br>(1960) | 1883.203 | RDBM TAG ROCK WALL DRAIN 15FT± E C/L SCHUEREN RD<br>1.65MI± SW STUNT RD OPP STA POST 11+06                | SY 6429   |
| MALIBU<br>(1960) | 1872.577 | RDBM TAG ROCK WALL DRAIN 15FT± E C/L SCHUEREN RD<br>1.7MI± SW STUNT RD                                    | SY 6430   |

| QUAD-YEAR        | ELEV     | D E S C R I P T I O N<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM NUMBER |
|------------------|----------|--|-----------|
| MALIBU<br>(1960) | 1828.153 | RDBM TAG CONC BASE ST SIGN NW COR PIUMA RD + SCHUEREN RD 3FT# N + 25FT# W C/L INT  | SY 6431   |
| MALIBU<br>(1960) | 1815.621 | SPK+T PP 1090560E SW COR PIUMA RD + SCHUEREN RD 15FT# S + 30FT# W C/L INT  | SY 6432   |
| MALIBU<br>(1960) | 1704.427 | CS TRI MON 3IN DN 45FT# W C/L RAMBLA PACIFICO 0.25MI# S SCHUEREN RD 10FT# N DR HSE 1601 MKD (LAS FLORES F4 1963) 2IN IP MKR 5FT# W | SY 6433   |
| MALIBU<br>(1960) | 1676.280 | RDBM TAG ROCK WALL DRAIN 20FT# W C/L RAMBLA PACIFICO 0.35MI# S SCHUEREN RD   | SY 6434   |
| MALIBU<br>(1960) | 1543.501 | RDBM TAG ROCK WALL DRAIN SW COR RAMBLA PACIFICO + LAS FLORES CANYON RD 18FT# W C/L OPP ARMY NIKE SITE                              | SY 6435   |
| MALIBU<br>(1960) | 1521.227 | RDBM TAG ROCK WALL DRAIN SW COR RAMBLA PACIFICO + LAS FLORES CANYON RD 15FT# W C/L + 250FT# S ENT ARMY NIKE SITE                   | SY 6436   |
| MALIBU<br>(1960) | 1421.456 | CS TRI MON 4IN DN ON RAMBLA PACIFICO 0.25MI# S LAS FLORES CANYON RD MKD (LAS FLORES G 5A 1963) 2IN IP MKR 4FT# S                   | SY 6437   |
| MALIBU<br>(1960) | 1381.309 | RDBM TAG ROCK WALL DRAIN 16FT# W C/L RAMBLA PACIFICO 0.3MI# S LAS FLORES CANYON RD   | SY 6438   |
| MALIBU<br>(1960) | 1203.495 | RDBM TAG ROCK WALL DRAIN 21FT# E C/L RAMBLA PACIFICO 0.7MI# S LAS FLORES CANYON RD NR STA POST 135+34                              | SY 6439   |
| MALIBU<br>(1960) | 1182.924 | CS TRI MON 3IN DN 60FT# W C/L RAMBLA PACIFICO 0.75MI# S LAS FLORES CANYON RD MKD (LAS FLORES F6 1963) 2IN IP MKR 4FT# N            | SY 6440   |
| MALIBU<br>(1960) | 1029.617 | RDBM TAG ROCK WALL DRAIN 12FT# E C/L RAMBLA PACIFICO 1.1MI# S LAS FLORES CANYON RD NR STA POST 118+34                              | SY 6441   |
| MALIBU<br>(1960) | 1025.248 | RDBM TAG ROCK WALL DRAIN 15FT# W C/L RAMBLA PACIFICO 1.1MI# S LAS FLORES CANYON RD   | SY 6442   |
| MALIBU<br>(1960) | 936.378  | RDBM TAG ROCK WALL DRAIN 30FT# N C/L RAMBLA PACIFICO 10FT# S SEMITAN AZURELEE DR   | SY 6443   |
| MALIBU<br>(1960) | 921.881  | CS MON 6IN UP NE COR RAMBLA PACIFICO + AZURELEE DR 23FT# N + 50FT# E C/L INT MKD (BM 64-7)   | SY 6444   |
| MALIBU<br>(1960) | 788.389  | CS MON 6IN UP SW COR RAMBLA PACIFICO + HUME RD 88FT# S + 23FT# W C/L INT MKD (BM 64-6)   | SY 6445   |
| MALIBU<br>(1960) | 704.676  | CS MON 6IN UP 22FT# E C/L RAMBLA PACIFICO 1.5MI# N PACIFIC COAST HWY MKD (BM 64-5)   | SY 6446   |
| MALIBU<br>(1960) | 558.814  | CS MON 6IN UP 28FT# W C/L RAMBLA PACIFICO 1.2MI# N PACIFIC COAST HWY MKD (BM 64-4)   | SY 6447   |
| MALIBU<br>(1960) | 438.860  | CS MON 6IN UP 25FT# E C/L RAMBLA PACIFICO 0.9MI# N PACIFIC COAST HWY MKD (BM 64-3)   | SY 6448   |
| MALIBU<br>(1960) | 244.418  | CS MON 6IN UP 27FT# E C/L RAMBLA PACIFICO 0.5MI# N PACIFIC COAST HWY MKD (BM 64-2)   | SY 6449   |
| MALIBU<br>(1960) | 84.031   | CS MON 4IN UP 20FT# W C/L RAMBLA PACIFICO 0.25MI# N PACIFIC COAST HWY MKD (BM 64-1)  | SY 6450   |
| MALIBU<br>(1960) | 618.479  | RDBM TAG CONC CB @ ENT CLARETVILLE 36FT# S C/L MULHOLLAND HWY 0.15MI# E LAS VIRGENES CANYON RD                                     | SY 6451   |

| QUAD-YEAR        | ELEV    | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM | NUMBER |
|------------------|---------|---|----|--------|
| MALIBU<br>(1960) | 626.425 | RDBM TAG ROCK WALL DRAIN 19FT± S C/L MULHOLLAND HWY 0.2MI± E LAS VIRGENES CANYON RD                             | SY | 6452   |
| MALIBU<br>(1960) | 623.671 | L+T CONC CB NW COR MULHOLLAND HWY + STOKES CANYON RD 125FT± N + 30FT± W C/L INT MKD (BM)                        | SY | 6453   |
| MALIBU<br>(1960) | 623.615 | L+T CONC CB NE COR MULHOLLAND HWY + STOKES CANYON RD 125FT± N + 30FT± E C/L INT MKD (BM)                        | SY | 6454   |
| MALIBU<br>(1960) | 672.031 | RDBM TAG ROCK WALL DRAIN 27FT± N C/L MULHOLLAND HWY 0.2MI± E STOKES CANYON RD NR STA POST 38+99                 | SY | 6455   |
| MALIBU<br>(1960) | 669.200 | RDBM TAG ROCK HDWL 23FT± S C/L MULHOLLAND HWY 0.2MI± E STOKES CANYON RD   | SY | 6456   |
| MALIBU<br>(1960) | 726.474 | RDBM TAG ROCK WALL DRAIN 24FT± S C/L MULHOLLAND HWY 0.5MI± E STOKES CANYON RD NR BC                             | SY | 6457   |
| MALIBU<br>(1960) | 760.402 | RDBM TAG ROCK WALL DRAIN 21FT± W C/L MULHOLLAND HWY 0.65MI± E STOKES CANYON RD                                  | SY | 6458   |
| MALIBU<br>(1960) | 793.959 | RDBM TAG ROCK WALL DRAIN 22FT± W C/L MULHOLLAND HWY 0.8MI± E STOKES CANYON RD                                   | SY | 6459   |
| MALIBU<br>(1960) | 806.571 | L+T ROCK WALL DRAIN 18FT± W C/L MULHOLLAND HWY 0.85MI± E STOKES CANYON RD                                       | SY | 6460   |
| MALIBU<br>(1960) | 836.928 | RDBM TAG ROCK WALL DRAIN 18FT± E C/L MULHOLLAND HWY 1.2MI± E STOKES CANYON RD                                   | SY | 6461   |
| MALIBU<br>(1960) | 816.543 | RDBM TAG ROCK WALL DRAIN 22FT± N C/L MULHOLLAND HWY 1.35MI± E STOKES CANYON RD NR STA POST 92+45                | SY | 6462   |
| MALIBU<br>(1960) | 819.296 | L+T ROCK WALL DRAIN 20FT± N C/L MULHOLLAND HWY 1.4MI± E STOKES CANYON RD MKD (BM)                               | SY | 6463   |
| MALIBU<br>(1960) | 887.205 | RDBM TAG ROCK WALL DRAIN 21FT± S C/L MULHOLLAND HWY 1.8MI± E STOKES CANYON RD                                   | SY | 6464   |
| MALIBU<br>(1960) | 877.737 | RDBM TAG ROCK WALL DRAIN 22FT± N C/L MULHOLLAND HWY 1.85MI± E STOKES CANYON RD NR STA POST 116+97               | SY | 6465   |
| MALIBU<br>(1960) | 861.026 | RDBM TAG ROCK WALL DRAIN 22FT± N C/L MULHOLLAND HWY 2.05MI± E STOKES CANYON RD NR STA POST 127+92               | SY | 6466   |
| MALIBU<br>(1960) | 861.031 | RDBM TAG ROCK WALL DRAIN 22FT± S C/L MULHOLLAND HWY 2.05MI± E STOKES CANYON RD OPP STA POST 127+92              | SY | 6467   |
| MALIBU<br>(1960) | 863.179 | RDBM TAG ROCK WALL DRAIN 17FT± S C/L MULHOLLAND HWY 2.45MI± E STOKES CANYON RD OPP STA POST 146+70              | SY | 6468   |
| MALIBU<br>(1960) | 883.316 | RDBM TAG ROCK HDWL 23FT± N C/L MULHOLLAND HWY 2.55MI± E STOKES CANYON RD NR STA POST 150+58                     | SY | 6469   |
| MALIBU<br>(1960) | 27.380  | RDBM TAG N CB 1FT± E BCR @ NE COR PACIFIC COAST HWY + BUSCH DR 40FT± N + 45FT± E C/L INT                        | SY | 6470   |
| MALIBU<br>(1960) | 38.306  | RDBM TAG CONC SPILLWAY OF DRAIN ON SE COR BUSCH DR + RAINSFORD PL 125FT± E + 12FT± S C/L INT NR CONC GUARD POST | SY | 6471   |
| MALIBU<br>(1960) | 53.296  | SPK+T PP NO 14542Y ON NE COR BUSCH DR + RAINSFORD PL 20FT± N + 100FT± E C/L INT                                 | SY | 6472   |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)   | BM NUMBER |
|------------------|----------|---|-----------|
| MALIBU<br>(1960) | 213.769  | 1 1/2IN IP + RE 2088 TAG 8IN UP ON PP LINE<br>35FT± W C/L MERRITT DR NR C/L PROD BUSCH DR   | SY 6473   |
| MALIBU<br>(1960) | 206.740  | L+T CONC APRON OF GARAGE 425FT± S C/L BUSCH DR<br>+ 66FT± E C/L MERRITT DR MKD (BM)   | SY 6474   |
| MALIBU<br>(1960) | 66.442   | RDBM TAG RUBBLE WALL @ SW COR MERRITT DR +<br>BADEN PL 120FT± S + 17FT± W C/L INT   | SY 6475   |
| MALIBU<br>(1960) | 68.805   | SPK + T PP NO 680259E ON SW COR MERRITT DR +<br>BADEN PL 130FT± S + 25FT± W C/L INT   | SY 6476   |
| MALIBU<br>(1960) | 50.866   | RDBM TAG CONC DR OF HSE 25FT± W C/L MORNING VIEW<br>DR + NR C/L PROD MERRITT DR   | SY 6477   |
| MALIBU<br>(1960) | 50.129   | 3/4IN IP + LS 2745 TAG ON SW COR MORNING VIEW DR<br>+ MERRITT DR 25FT± W + 30FT± S C/L INT  | SY 6478   |
| MALIBU<br>(1960) | 1071.200 | RDBM TAG NR CTR E WALL 36FT N APPROX C/L<br>MULHOLLAND HWY + 130FT W APPROX C/L OLD<br>TOPANGA CANYON RD  | SY 6771   |
| MALIBU<br>(1960) | 1071.502 | RDBM TAG ROCK WALL OF DRAIN 20FT N APPROX C/L<br>MULHOLLAND HWY + 225FT W APPROX C/L OLD<br>TOPANGA CANYON RD   | SY 6772   |
| MALIBU<br>(1960) | 1186.390 | L+BN N EDGE CONC APRON @ 3442 DOROTHY DR 18FT<br>E C/L + 95FT S APPROX C/L OLD TOPANGA CANYON RD  | SY 6773   |
| MALIBU<br>(1960) | 1261.174 | RDBM TAG E WALL OPEN DRAIN 55FT W C/L INT VALDEZ<br>RD + OLD TOPANGA CANYON RD  | SY 6774   |
| MALIBU<br>(1960) | 1359.028 | L+T TOP ROCK OUTCROP 25FT S C/L OLD TOPANGA<br>CANYON RD + 1.0MI S INT MULHOLLAND HWY + OLD<br>TOPANGA CANYON RD ACROSS FROM HSE 3141                                       | SY 6775   |
| MALIBU<br>(1960) | 1411.973 | RDBM TAG ROCK OUTCROP 20FT W C/L OLD TOPANGA<br>CANYON RD + 1.2MI S INT MULHOLLAND HWY + OLD<br>TOPANGA CANYON RD 35FT NE MILE POST 239+60                                  | SY 6776   |
| MALIBU<br>(1960) | 1525.246 | RDBM TAG NW CONC FOOTING OF GATE POST TO SUMMIT<br>MOTORWAY 60FT E APPROX C/L OLD TOPANGA CANYON<br>RD 1.7MI S INT MULHOLLAND HWY + OLD TOPANGA<br>CANYON RD                | SY 6777   |
| MALIBU<br>(1960) | 1519.317 | RDBM TAG CONC FOOTING 6FT CHAIN LINK FENCE @ COR<br>40FT W APPROX C/L OLD TOPANGA CANYON RD 1.7MI S<br>INT MULHOLLAND HWY + OLD TOPANGA CANYON RD                           | SY 6778   |
| MALIBU<br>(1960) | 1364.431 | RDBM TAG COLLAR FIRE HYD 20FT N APPROX C/L OLD<br>TOPANGA CANYON RD + 2.2MI S INT MULHOLLAND HWY<br>+ OLD TOPANGA CANYON RD 95FT E STA POST 189+70<br>NR HSE 2367           | SY 6779   |
| MALIBU<br>(1960) | 1362.930 | L+BN CONC OF GATE SLIDE @ HSE 2370 40FT S APPROX<br>C/L OLD TOPANGA CANYON RD + 2.2MI S INT<br>MULHOLLAND HWY + OLD TOPANGA CANYON RD                                       | SY 6780   |
| MALIBU<br>(1960) | 1209.881 | RDBM TAG COLLAR FIRE HYD 20FT N APPROX C/L OLD<br>TOPANGA CANYON RD + 2.7MI S INT MULHOLLAND HWY<br>+ OLD TOPANGA CANYON RD 150FT E STA POST 165+41                         | SY 6781   |
| MALIBU<br>(1960) | 1198.592 | CSBM MON NR CTR CLUMP OAK TREES 15FT S APPROX<br>C/L OLD TOPANGA CANYON RD + 2.75MI S INT<br>MULHOLLAND HWY + OLD TOPANGA CANYON RD 100FT W<br>STA POST 165+41 MKD(BM OT 9) | SY 6782   |
| MALIBU<br>(1960) | 1144.811 | RDBM TAG COLLAR FIRE HYD 20FT W APPROX C/L<br>OLD TOPANGA CANYON RD + 3.2MI S INT MULHOLLAND<br>HWY + OLD TOPANGA CANYON RD NR ENT HSE 23340                                | SY 6783   |

| QUAD-YEAR        | ELEV     | DESCRIPTION<br>(INCLUDE QUAD AND YEAR IN DESCRIPTION)  | BM NUMBER |
|------------------|----------|--|-----------|
| MALIBU<br>(1960) | 1100.061 | RDBM TAG COLLAR FIRE HYD 25FT N APPROX C/L OLD TOPANGA CANYON RD + 3.5MI S INT MULHOLLAND HWY + OLD TOPANGA CANYON RD  | SY 6784   |
| MALIBU<br>(1960) | 1101.548 | CS MON FLUSH NR ENT HSE 1717 45FT NW APPROX C/L OLD TOPANGA CANYON RD + 3.5MI S INT MULHOLLAND HWY + OLD TOPANGA CANYON RD 9FT W 24IN OAK TREE MKD (BM OT 8) | SY 6785   |
| MALIBU<br>(1960) | 1020.625 | CS MON FLUSH IN CB @ COR CHURCH SW COR OLD TOPANGA CANYON RD + VALLEY DR 30FT S + 40FT W APPROX C/L INT MKD (BM OT 7)  | SY 6786   |
| MALIBU<br>(1960) | 1018.718 | L+BN COR PORCH OF CHURCH SW COR OLD TOPANGA CANYON RD + VALLEY DR 80FT S + 30FT W APPROX C/L INT MKD (BM)  | SY 6787   |
| MALIBU<br>(1960) | 1002.575 | L+T SW COR SLAB PORCH @ HSE 1322 48FT E C/L OLD TOPANGA CANYON RD + 50FT N C/L BONNELL DR  | SY 6788   |
| MALIBU<br>(1960) | 984.155  | RDBM TAG CONC + ROCK WALL BRIDGE B750 NW COR OLD TOPANGA CANYON RD + RED ROCK RD 135FT W + 20FT N APPROX C/L INT   | SY 6789   |
| MALIBU<br>(1960) | 983.236  | L+BN CONC FOOTING GATE TO HSE 1268 24FT N APPROX C/L OLD TOPANGA CANYON RD + 43FT W APPROX C/L RED ROCK RD MKD (BM)  | SY 6790   |
| MALIBU<br>(1960) | 922.059  | RD HD SPK+L CB BRIDGE B758 12FT N C/L OLD TOPANGA CANYON RD + 0.5MI E INT OLD TOPANGA CANYON RD + RED ROCK RD CB MKD (SKY 1)                                 | SY 6791   |
| MALIBU<br>(1960) | 903.172  | SPK+L CONC ABUT BRIDGE TO HSE 913 24FT W APPROX C/L OLD TOPANGA CANYON RD + 0.6MI E INT OLD TOPANGA CANYON RD + RED ROCK RD                                  | SY 6792   |
| MALIBU<br>(1960) | 851.086  | RD HD SPK CONC ABUT BRIDGE TO HSE 649 40FT W APPROX C/L OLD TOPANGA CANYON RD + 1.0MI E INT OLD TOPANGA CANYON RD + RED ROCK RD                              | SY 6793   |
| MALIBU<br>(1960) | 851.573  | RDBM TAG CONC FOOTING FIRE HYD GUARD POST 25FT W APPROX C/L OLD TOPANGA CANYON RD 1.0MI E INT OLD TOPANGA CANYON RD + RED ROCK RD NR ENT HSE 649             | SY 6794   |
| MALIBU<br>(1960) | 783.901  | L+T CONC CB BRIDGE B759 13FT N APPROX C/L OLD TOPANGA CANYON RD + 1.5MI E INT OLD TOPANGA CANYON RD + RED ROCK RD MKD (BM)                                   | SY 6795   |
| MALIBU<br>(1960) | 779.627  | L+T CONC STEP CHURCH 40FT S APPROX C/L OLD TOPANGA CANYON RD + 1.6MI E INT OLD TOPANGA CANYON RD + RED ROCK RD MKD (BM)                                      | SY 6796   |
| MALIBU<br>(1960) | 751.557  | L+T CONC ABUT BRIDGE B423 @ OLD TOPANGA CANYON RD + NEW TOPANGA CANYON RD (TOPANGA CANYON BLVD) 20FT S + 85FT W APPROX C/L INT                               | SY 6797   |
| MALIBU<br>(1960) | 752.666  | L+T CONC FOOTING LIGHT STANDARD NE COR OLD TOPANGA CANYON RD + NEW TOPANGA CANYON RD (TOPANGA CANYON BLVD) 80FT N + 30FT E APPROX C/L INT                    | SY 6798   |